

03902751

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

SOS-1

Vehicle Standards and Insp
Box 45064 Regent Postal Out
Winnipeg, MB, R2C 5G7
1-204-985-0920

Manitoba

Date Inspection Started DAY: 07 MO: 11 YR: 24	Station Number A5593	Station Name JLS Truck Repair	City Winkler	Phone Number 204-332-0407
Date Inspection Completed DAY: 07 MO: 11 YR: 24	Mechanic Number M51840	Mechanic Signature <i>[Signature]</i>	Station Phone Number 204-332-0407	
Inspection Expiry Date DAY: 30 MO: 11 YR: 25	Vehicle Owner City of Winkler	Address 185 Main Street Winkler MB	Postal Code R6W 1B4	Phone 204-325-9624

<input checked="" type="checkbox"/> Pass/Safe Vehicle	Licence Number CKIK1259	Prov. MB	NSC # MB7028937	Odometer Reading 227692	Odom. Type <input checked="" type="checkbox"/> km <input type="checkbox"/> mi
<input checked="" type="checkbox"/> Fail/Unsafe Vehicle	Vehicle Identification Number 2FZ1HAWC1Y081A2641556	Make Sterling	Model Voc.	Year 2008	Unit # U200
<input type="checkbox"/> Fail/Hazardous	<input checked="" type="checkbox"/> Confirmed legible Vehicle Identification Number on vehicle				

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

☒ Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
X	X	Section 1 - Power Train: Defects (if any) 4(d) - Loose bolts on drive line																																																																						
X		Section 2 Suspension: Defects (if any)																																																																						
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																						
		Brake Inspection Type: A (B) C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>13/16</td> <td>13/16</td> <td>16.532</td> <td>16.536</td> <td>1.25</td> <td>1.25</td> </tr> <tr> <td>2</td> <td>9/16</td> <td>9/16</td> <td>16.547</td> <td>16.552</td> <td>1.25</td> <td>1.25</td> </tr> <tr> <td>3</td> <td>9/16</td> <td>9/16</td> <td>16.545</td> <td>16.557</td> <td>1.25</td> <td>1.25</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	13/16	13/16	16.532	16.536	1.25	1.25	2	9/16	9/16	16.547	16.552	1.25	1.25	3	9/16	9/16	16.545	16.557	1.25	1.25	4							5							Final Measurement																					
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	13/16	13/16	16.532	16.536	1.25	1.25																																																																		
2	9/16	9/16	16.547	16.552	1.25	1.25																																																																		
3	9/16	9/16	16.545	16.557	1.25	1.25																																																																		
4																																																																								
5																																																																								
Final Measurement																																																																								
X		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X	X	Section 6 - Lamps: Defects (if any) 2(a) - Reflector																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X		Section 8 - Body: Defects (if any)																																																																						
X		Section 9 - Tire & Wheel: Defects (if any)																																																																						
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>19/32</td> <td>20/32</td> <td></td> <td></td> <td>95</td> <td>95</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>23/32</td> <td>23/32</td> <td>23/32</td> <td>23/32</td> <td>95</td> <td>85</td> <td>85</td> <td>90</td> </tr> <tr> <td>3</td> <td>17/32</td> <td>17/32</td> <td>16/32</td> <td>23/32</td> <td>85</td> <td>85</td> <td>85</td> <td>90</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	19/32	20/32			95	95			2	23/32	23/32	23/32	23/32	95	85	85	90	3	17/32	17/32	16/32	23/32	85	85	85	90	4									5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	19/32	20/32			95	95																																																																		
2	23/32	23/32	23/32	23/32	95	85	85	90																																																																
3	17/32	17/32	16/32	23/32	85	85	85	90																																																																
4																																																																								
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.