

04075930

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba SOS-2

Box 43264 Regent Postal Cntr. Winnipeg, MB, R2C 6C7 1-204-985-0920

Manitoba C078286

Date Inspection Started: 02 DAY, 06 MO, 26 YR
 Date Inspection Completed: 02 DAY, 06 MO, 26 YR
 Inspection Expiry Date: 30 DAY, 06 MO, 27 YR

Station Number: A105109 Station Name: Scharf Service Ltd
 Mechanic Number: M21416 Mechanic Signature: [Signature] Station Phone Number: 204-242-2785

Vehicle Owner: Subcan Ltd
 Address: 150 Front Ave City: Manitoba Province: MB Postal Code: R0G-1G0 Phone: 242-2845

License Number: C4X437 Prov: MB NSC #: Odometer Reading: Odom. Type: km mi

Vehicle Identification Number: 1M42010J23C4081204 Make: Wells Cargo Model: Cargo Year: 2012 Unit #: TT36
 Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck G/VWR KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
		Section 1 - Power Train: Defects (if any)																																																																							
X		Section 2 Suspension: Defects (if any)																																																																							
X	X	Section 3 - Brake Systems: 3H 3A Electric Defects (if any) Circle Brake Type 2nd brake pedal arms seized Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection <table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining MM</th> <th colspan="2">Drum/Rotor MM</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>3.67</td> <td>3.90</td> <td>305.99</td> <td>305.41</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>3.98</td> <td>3.99</td> <td>305.74</td> <td>305.77</td> <td></td> <td></td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Lining MM		Drum/Rotor MM		Stroke		L	R	L	R	L	R	1	3.67	3.90	305.99	305.41			2	3.98	3.99	305.74	305.77			3							4							5																													
Axle	Lining MM			Drum/Rotor MM		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	3.67	3.90	305.99	305.41																																																																					
2	3.98	3.99	305.74	305.77																																																																					
3																																																																									
4																																																																									
5																																																																									
		Section 4 - Steering: Defects (if any)																																																																							
		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
X	X	Section 6 - Lamps: Defects (if any) g.e. left rear clearance light																																																																							
X		Section 7 - Electrical System: Defects (if any)																																																																							
X		Section 8 - Body: Defects (if any)																																																																							
X		Section 9 - Tire & Wheel: Defects (if any)																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>5.42</td> <td>5.47</td> <td></td> <td></td> <td>50</td> <td>50</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>5.57</td> <td>5.53</td> <td></td> <td></td> <td>50</td> <td>50</td> <td></td> <td></td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	5.42	5.47			50	50			2	5.57	5.53			50	50			3									4									5								
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	5.42	5.47			50	50																																																																			
2	5.57	5.53			50	50																																																																			
3																																																																									
4																																																																									
5																																																																									
X		Section 10 - Coupling Devices: Defects (if any)																																																																							

- THIS INSPECTION IS NOT A WARRANTY - This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date: