



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: PA11010
Decal Expiry Date: 2026-Nov-30
Inspection Number: 21779658

Inspection Result:

PASS

FACILITY: NORTHERN B.C. TRUCKERS / NS398
INSPECTOR: SCHROEDER, COLIN LESLIE / 109354
WORK ORDER #:
INSPECTION TYPE: Complete
INSPECTION CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSPECTION REASON: Semi-annual
INSPECTION START: 2026-May-21 07:00 AM PST
INSPECTION COMPLETE: 2026-May-21 08:00 AM PST

S06-1

VEHICLE JUR: British Columbia
PLATE #: 5670JA
LICENCED GVW(kg): 25000
VEHICLE YEAR: 2005
MAKE: STERLING
MODEL:
REGI: 02951105
UNIT/FLEET#: T111
BODY STYLE: Van
ODOMETER: 73911 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2FZHAZDEX5AUB4604
OWNER/LESSEE NAME: TRACKER CONTRACTING, LTD
ADDRESS: 13168 267RD
Fort St John, British Columbia
V1J8E2, Canada

Vehicle Identification (VIN) Passed
Section 1 - Power Train Passed
Section 2 - Suspension Passed
Section 3 - Brake System Not Applicable
Section 3A - Air Brakes Passed
Section 3H - Hydraulic Brakes Not Applicable
Section 4 - Steering Passed
Section 5 - Instruments and Auxiliary Equipment Passed
Section 6 - Lamps Passed
Section 7 - Electrical System Passed
Section 8 - Frame and Body Passed
Section 9A - Tires Passed
Section 9B - Wheels Passed
Section 10 - Coupling Devices Not Applicable
Section 11 - Other Vehicle Components Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	24	Automatic	30	31	10				✓
2	Clamp	30L	Automatic	37	35	14	14	14	14	
3	Clamp	30L	Automatic	35	37	8	8	8	8	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right	Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)				
			Lining/Pad		Left	Right	Rotor/Drum	Left	Right
1	50	49	Lining (Shoe)	18	18		Drum		
2	55	57	Lining (Shoe)	17	17		Drum		
3	61	62	Lining (Shoe)	16	16		Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: SCHROEDER, COLIN LESLIE

Road Test Date:
Signature:

Colin Schroeder

This Inspection Report was submitted to CVSE on 2026-May-21 10:21 AM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 2b of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement.

CVSE014

5/25/2026 10:07:43 AM PST