



Commercial Vehicle Inspection Report

Decal Number: GN83339
Decal Expiry Date: 2027-Jan-31
Inspection Number: 21836620

Inspection Result:

PASS

FACILITY:	PATTAR WELDING LTD. / S20278	INSP. TYPE:	Complete	INSP. START:	2026-Jul-03 05:30 PM PDT
INSPECTOR:	KAHLON, HARINDER SINGH / 301006	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Jul-04 10:30 AM PDT
WORK ORDER #:		INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	13169340	VIN:	1NPXL40X5LD647252
PLATE #:	NW9036	UNIT/FLEET#:	936	OWNER/LESSEE NAME:	CWB NATIONAL LEASING INC. (LESSOR), SIDHU BROTHER TRUCKING LTD(LESSEE)
LICENCED GVW(kg):	63500	BODY STYLE:	Dump Truck	ADDRESS:	5749 MCKEE ST
VEHICLE YEAR:	2020	ODOMETER:	388654 KM		Burnaby, British Columbia
MAKE:	PETERBILT	HUB ODOMETER:			V5J 2V2, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) ABS MODULE REPLACED
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) MARKER LIGHTS REPAIRED
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	35	35	15			15	✓
2	Clamp	30L	Automatic	37	38	17	17	17	17	
3	Clamp	30L	Automatic	36	37	20	20	20	20	
Comment:				Comment:						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	54	57	Lining (Shoe)	16	16	Drum		
2	59	62	Lining (Shoe)	14	14	Drum		
3	65	67	Lining (Shoe)	16	16	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: KAHLON, HARINDER SINGH
Road Test Date: 
Signature: _____
Road Tester: _____

This Inspection Report was submitted to CVSE on 2026-Jul-05 11:06 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

7/5/2026 11:07:09 AM PDT