



Commercial Vehicle Inspection Report

Decal Number: PA17000
Decal Expiry Date: 2027-Feb-28
Inspection Number: 21881733

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS' /
N5398
INSPECTOR: SCHROEDER, COLIN LESLIE /
109354
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW
5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2026-Aug-13 11:15 AM MST
INSP. COMPLETE: 2026-Aug-13 12:09 PM MST

506-2

VEHICLE JUR: British Columbia
PLATE #: MB0605
LICENCED GVW(kg): 24500
VEHICLE YEAR: 2007
MAKE: STERLING
MODEL:

REGI: 12453353
UNIT/FLEET#: T142
BODY STYLE: Dump Truck
ODOMETER: 62326 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 2FZAATDJ27AX68909
OWNER/LESSEE NAME: TRACKER CONTRACTING, LTD
ADDRESS: 13168 267 RD
Fort St John, British Columbia
V1J8E2, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

WINDSHIELD CHIPS

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	30	31	12			12	✓
2	Clamp	30L	Automatic	38	37	11	11	11	11	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)				
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	50	51	Lining (Shoe)	18	18	Drum			
2	69	68	Lining (Shoe)	14	14	Drum			
Comment:			Comment:		Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.				

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: SCHROEDER, COLIN LESLIE
Road Test Date: 
Signature: 
Road Tester:

This Inspection Report was submitted to CVSE on 2026-Aug-13 12:10 PM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

8/13/2026 12:10:23 PM MST