



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GN00717
Decal Expiry Date: 2026-Sep-30
Inspection Number: 21717162

506-4
Inspection Result:
PASS

2026253

FACILITY: A&A TRUCK & TRAILER REPAIR LTD. / S11370
INSPECTOR: DHALIWAL, HARJINDER SINGH / 115079
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2026-Mar-31 12:00 PM PDT
INSP. COMPLETE: 2026-Mar-31 02:00 PM PDT

VEHICLE JUR: British Columbia
PLATE #: XS1527
LICENCED GVW(kg): 61500
VEHICLE YEAR: 2019
MAKE: PETERBILT
MODEL:

REGI: 12648587
UNIT/FLEET#: 108
BODY STYLE: Dump Truck
ODOMETER: 541517 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 1NP1L40X4KD495185
OWNER/LESSEE NAME: SIDHU BROTHER TRUCKING, LTD
SIDHU BROTHER TRUCKING LTD.
ADDRESS: 7557 LAMBETH DR, 7557 LAMBETH DR
Burnaby, British Columbia
V5E 4A5, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) XL2 ,AND XL3 B/S REPLACED SHOCK
Section 3 - Brake System	Repaired (same day) XL2 R/S REPLACED BRAKES AND DRUMS
Section 3A - Air Brakes	Repaired (same day) XL2 R/S MAXI AIR LINE REPLACED
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxilliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) MARKER LIGHT FIXED
Section 7 - Electrical System	Repaired (same day) CITY HORN FIXED
Section 8 - Frame and Body	Repaired (same day) XL2 TORQUE ARM REPLACED
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	35	35
2	Clamp	30L	Automatic	36	36
3	Clamp	30L	Automatic	36	36

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
14			14	✓
11	11	11	11	
8	8	8	8	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	0	0
2	0	0
3	0	0

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	12	12
Lining (Shoe)	14	12
Lining (Shoe)	14	13

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	419.82	419.83
Drum	419.65	419.84
Drum	419.63	419.80

Comment:

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: DHALIWAL, HARJINDER SINGH

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Mar-31 07:14 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCV/P at the Commercial Vehicle Safety Enforcement

CVSE014

3/31/2026 7:14:40 PM PDT