



Commercial Vehicle Inspection Report

Decal Number: GN83319
Decal Expiry Date: 2026-Dec-31
Inspection Number: 21804833

Inspection Result:

PASS

FACILITY: PATTAR WELDING LTD. / S20278
INSPECTOR: KAHLOH, HARINDER SINGH / 301006
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2026-Jun-06 10:30 PM PDT
INSP. COMPLETE: 2026-Jun-07 11:20 AM PDT

VEHICLE JUR: British Columbia
PLATE #: XM5043
LICENCED GVW(kg): 12494
VEHICLE YEAR: 2019
MAKE: KENWORTH
MODEL:

REGI: 12593118
UNIT/FLEET#: 207
BODY STYLE: Dump Truck
ODOMETER: 465531 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 1NKZL40X9KJ997255
OWNER/LESSEE NAME: SIDHU BROTHER TRUCKING, LTD
ADDRESS: 7557 LAMBETH DR
Burnaby, British Columbia
V5E 4A5, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) XL#2 SUSPENSION BUSHING BOLTS TIGHTEN
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) AIR LEAK FIX
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) WINDSHIELD REPLACED
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	34	34	14			15	✓
2	Clamp	30L	Automatic	38	37	11	9	10	9	
3	Clamp	30L	Automatic	38	38	13	13	13	13	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	37	35
2	41	58
3	42	40

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	16
Lining (Shoe)	19	16
Lining (Shoe)	19	19

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: KAHLOH, HARINDER SINGH

Signature:

This Inspection Report was submitted to CVSE on 2026-Jun-08 03:30 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 215 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

6/8/2026 3:30:10 PM PDT