



Commercial Vehicle Inspection Report

Decal Number: GN15959
Decal Expiry Date: 2026-Oct-31
Inspection Number: 21721851

506-8
Inspection Result:
PASS

FACILITY: PATTAR WELDING LTD. / S20278
INSPECTOR: KAHLOH, HARINDER SINGH / 301006
WORK ORDER #:
INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual
INSP. START: 2026-Apr-01 11:00 AM PDT
INSP. COMPLETE: 2026-Apr-03 04:00 PM PDT

VEHICLE JUR: British Columbia
PLATE #: XS1525
LICENCED GVW(kg): 61000
VEHICLE YEAR: 2016
MAKE: PETERBILT
MODEL:
REGI: 11474456
UNIT/FLEET#: 216
BODY STYLE: Dump Truck
ODOMETER: 692816 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2NPXL40X2GM305385
OWNER/LESSEE NAME: SIDHU BROTHER TRUCKING, LTD
ADDRESS: 7557 LAMBETH DR
Burnaby, British Columbia
V5E 4A5, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) NEW FRONT DRIVESHAFT, NEW CENTER BEARING & JOINTS. FAN HUB REPLACED
Section 2 - Suspension	Repaired (same day) XL#2 RIGHT & XL#3 LEFT AIRBAG REPLACED. REAR TORQUE ARM BUSHING REPLACED
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) MULTIPLE AIR LEAKS FIX
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) MULTIPLE MARKER LIGHTS FIX
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) BOX CRACKS WELD. TARP REPLACED
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	24L	Automatic	36	36	17			12	✓
2	Clamp	30L	Automatic	38	38	7	7	7	7	
3	Clamp	30L	Automatic	37	38	13	13	13	13	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	48	47
2	59	62
3	67	64

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	16
Lining (Shoe)	13	13
Lining (Shoe)	13	13

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	419.69	419.62
Drum	419.87	419.83
Drum	419.94	419.97

Comment:

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Inspector: KAHLOH, HARINDER SINGH

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Apr-04 12:52 PMPDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

4/4/2026 12:52:44 PM PDT