



Commercial Vehicle Inspection Report

Decal Number: GP53319
Decal Expiry Date: 2027-Aug-31
Inspection Number: 21892276

510-18
2026253
Inspection Result:
PASS

FACILITY: ONE STOP TRUCK CENTRE LTD. / S20504
INSPECTOR: Nelson, Jerry John / 201387
WORK ORDER #:

INSPECTION TYPE: Complete
INSPECTION CLASS: Class 3 - Trailer and Semi-Trailer
INSPECTION REASON: Annual

INSPECTION START: 2026-Aug-22 09:30 AM PDT
INSPECTION COMPLETE: 2026-Aug-22 10:30 AM PDT

VEHICLE JURISDICTION: British Columbia
PLATE #: 56658K
PERMITTED GVW(kg): 0

REGISTRATION: 14501353
UNIT/FLEET#:
BODY STYLE: LOWBOY TRAILER

VIN: 1W8A11E39FS000268
OWNER/LESSEE NAME: KONDOLAY TRANSPORT LTD.,
ADDRESS: 2015 PEARDONVILLE, 2015 PEARDONVILLE
Abbotsford, British Columbia
V2T 6J7, Canada

VEHICLE YEAR: 2015
MAKE: WITZCO
MODEL: RG50

ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) CHANGE BOTH #1 AND #2 & #3 LEFT BRAKES
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	3	32	9	10	10	10	
2	Clamp	30	Automatic	34	34	11	11	14	14	
3	Clamp	30	Automatic	34	34	14	14	14	14	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	125	125	Lining (Shoe)	9	9	Drum		
2	125	60	Lining (Shoe)	9	16	Drum		
3	125	55	Lining (Shoe)	9	17	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: Nelson, Jerry John
Road Test Date:
Signature:
Road Tester:

This Inspection Report was submitted to CVSE on 2026-Aug-22 01:20 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.