



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GF37838
Decal Expiry Date: 2025-Oct-31
Inspection Number: 21124983

Inspection Result:
PASS

FACILITY: ARSARA DIESEL TRUCK / S5708
INSPECTOR: Bhachu, Sukhjinder Singh / 201670
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual

INSP. START: 2024-Oct-29 01:30 PM PDT
INSP. COMPLETE: 2024-Oct-29 06:11 PM PDT

VEHICLE JUR: Washington

PLATE #:

LICENCED GVW(kg): 0

VEHICLE YEAR: 2022

MAKE: DELUCIO

MODEL: VAN

REGI:
UNIT/FLEET#: V1001
BODY STYLE: Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE: Not Applicable

VIN: 7LVD5DD26ND010370
OWNER/LESSEE NAME: TRANSHUB LOGISTICS LTD.,
ADDRESS: 27-5858 132 ST
Surrey, British Columbia
V3X1N1, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) 1ST XL L'S MAXI
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Repaired (same day) PLATE LIGHT
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axes	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	30	35
2	Clamp	30	Automatic	25	30

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
10	11	11	11	
10	10	11	11	

Comment:

Air Brake Camshaft Rotation (degrees)

Axes	Left	Right
1	60	60
2	70	75

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	16
Lining (Shoe)	14	14

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: Bhachu, Sukhjinder Singh

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2024-Oct-29 06:11 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

10/29/2024 6:11:49 PM PDT