



# Commercial Vehicle Inspection Report

Decal Number: GH71300  
Decal Expiry Date: 2026-Feb-28  
Inspection Number: 21226885

Inspection Result:  
**PASS**

FACILITY: ARSARA DIESEL TRUCK / S5708 INSP. TYPE: Complete INSP. START: 2025-Feb-02 09:00 AM PST  
INSPECTOR: SANDHU, SHAMSHER SINGH / 114059 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2025-Feb-03 12:50 PM PST  
INSP. REASON: Annual

## WORK ORDER #:

VEHICLE JUR: British Columbia REGI: 13993198 VIN: 2M592161XK1179595  
PLATE #: 36807K UNIT/FLEET#: V1007 OWNER/LESSEE NAME: MERIDIAN ONECAP CREDIT CORP.(LESSOR), TRANSHUB LOGISTICS LTD.(LESSE)  
LICENCED GVW(kg): 0 BODY STYLE: Van Trailer ADDRESS: PO BOX 98057 SCOTTSDALE PO  
VEHICLE YEAR: 2019 ODOMETER: Delta, British Columbia  
MAKE: MANAC HUB ODOMETER: V4E3M9, Canada  
MODEL: BRAKE TYPE: Air  
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axes	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	34	34	5	5	7	5	
2	Clamp	30	Automatic	36	35	6	5	15	15	
Comment: 2XL R/S BRAKE DRUM REPLACED						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axes	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	60	60	Lining (Shoe)	14	14	Drum		
2	65	95	Lining (Shoe)	14	12	Drum		
Comment:			Comment: 2XL R/S BRAKE DRUM REPLACED			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments: 2XL R/S BRAKE DRUM REPLACED , R/S TOP FRONT LIGHT REPLACED  
Has this Vehicle been road tested? No Road Test Date: Signature: Road Tester:

This Inspection Report was submitted to CVSE on 2025-Feb-03 12:50 PMPST  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSED014

2/3/2025 12:50:34 PM PST