



Commercial Vehicle Inspection Report

Decal Number: GP11066
Decal Expiry Date: 2027-Jan-31
Inspection Number: 21849186

Inspection Result:

PASS

FACILITY: THAT'S TRUCK'N REPAIRS INC. / S11860
INSPECTOR: BAEKGAARD, BRIAN JAMES / 114585
WORK ORDER #:
INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual
INSP. START: 2026-Jul-10 03:00 PM PDT
INSP. COMPLETE: 2026-Jul-10 05:00 PM PDT

VEHICLE JUR: British Columbia
PLATE #: LT7166
LICENCED GVW(kg): 17200
VEHICLE YEAR: 2005
MAKE: FREIGHTLIN
MODEL:
REGI: 02598228
UNIT/FLEET#:
BODY STYLE: Truck Tractor
ODOMETER: 489115 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 1FUBCXDJ45HU23970
OWNER/LESSEE NAME: 575580, BC LTD
ADDRESS: 1432 20TH ST
Cranbrook, British Columbia
V1C6M3, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20L	Automatic	35	35	13			13	✓
2	Clamp	30L	Automatic	35	35	13	15	15	13	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	60	60
2	60	60

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	15
Lining (Shoe)	15	15

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: BAEKGAARD, BRIAN JAMES
Road Test Date:
Road Tester:
Signature: _____

This Inspection Report was submitted to CVSE on 2026-Jul-15 11:38 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement

CVSE0014

7/15/2026 11:38:45 PM PDT