S14-1

Commercial Vehicle Inspection Report

Decal Number: GK27380
Decal Expiry Date: 2026-Nov-30
Inspection Number: 21567185

Inspection Result: **PASS**

2026282

FACILITY:	B. B. TRANSPORT SYSTEMS LTD. / S15440	**INSP. TYPE:**	Complete	**INSP. START:**	2025-Nov-14 04:28 AM PST
INSPECTOR:	LOEWEN, DEVIN JOHN / 113976	**INSP. CLASS:**	Class 3 - Trailer and Semi-Trailer	**INSP. COMPLETE:**	2025-Nov-14 06:28 AM PST
WORK ORDER #:		**INSP. REASON:**	Annual		

VEHICLE JUR:	British Columbia	**REGI:**	10983518	**VIN:**	2LDPF3231EJ058023
PLATE #:	02012j	**UNIT/FLEET#:**	601	**OWNER/LESSEE NAME:**	MARPOLE TRANSPORT, LTD
LICENCED GVW(kg):	999999	**BODY STYLE:**	Flat Deck Trailer	**ADDRESS:**	7086 BROWN ST, 7086 BROWN ST
VEHICLE YEAR:	2014	**ODOMETER:**			Delta, British Columbia
MAKE:	LODE KING	**HUB ODOMETER:**	73552 KM		V4G1G8, Canada
MODEL:		**BRAKE TYPE:**	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30L	Automatic	30	30
2	Clamp	30L	Automatic	30	30
3	Clamp	30L	Automatic	30	30

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
12	14	9	10	
13	11	8	11	
14	14	10	9	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	40	40
2	80	40
3	40	80

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	18
Lining (Shoe)	13	18
Lining (Shoe)	17	13

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:**

Inspector: LOEWEN, DEVIN JOHN **Signature:** **Road Tester:**

This Inspection Report was submitted to CVSE on 2025-Nov-14 06:28 AM PST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.
The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement