

QUAN.	DESCRIPTION	AMOUNT
1	108975-20AM BATON CUTEH	
1	455 CK101 INSULATION KIT	
1	FLINTHOPE MACHINES	
TOTAL PARTS		
SUBLET		
TOTAL SUBLET		



L.M.B. TRANSPORT INC.
 P.O. BOX 8
 CANNIFTON, ONTARIO K0K 1K0
 TEL: (613) 968-7541 FAX: (613) 968-7541
 HST NO: R129359477

36163

NAME	LMB #167	DATE	JAN 27/25	MAKE	PETE
ADDRESS		TYPE-MODEL	CONU	YR	2013
CITY		PHONE		MILEAGE	1100235
				LIC.	
				SERIAL NO.	ON FILE
INSTRUCTIONS					AMOUNT
- ROR SCOUTER					
- ROR INPUT START KIT					
- EXCHANGE TRIMS FROM #161 POWER					
NOTES:					LABOUR
					PARTS
TOTAL SUBLET					SUBLET
All estimates are for labour only. Material additional. This company does not assume any responsibility whatever for vehicle or equipment left for repairs, storage or other purposes, or for articles left in same. Vehicle driven by our employees at owner's risk.					HST
I hereby authorize the above work to be done along with necessary materials.					TOTAL AMOUNT
I hereby acknowledge my indebtedness in the amount of \$					

QUAN.	DESCRIPTION	AMOUNT
2	HOOD CABLES HLK 2044	
TOTAL PARTS		
SUBLET		
TOTAL SUBLET		



L.M.B. TRANSPORT INC.
 P.O. BOX 8
 CANNIFTON, ONTARIO K0K 1K0
 TEL: (613) 968-7541 FAX: (613) 968-7541
 HST NO: R129359477

36227


NAME	LMB #167	DATE	JAN 30/25	MAKE	PETER
ADDRESS		TYPE-MODEL		YR	
CITY		PHONE		MILEAGE	1119513
				LIC.	
				SERIAL NO.	ON FILE
INSTRUCTIONS					AMOUNT
- REPLACES HOOD CABLES					
- REPAIR BUMPER CLAMP HORN					
- REPAIR LINE @ TURBO					
NOTES:					LABOUR
					PARTS
TOTAL SUBLET					SUBLET
All estimates are for labour only. Material additional. This company does not assume any responsibility whatever for vehicle or equipment left for repairs, storage or other purposes, or for articles left in same. Vehicle driven by our employees at owner's risk.					HST
I hereby authorize the above work to be done along with necessary materials.					TOTAL AMOUNT
I hereby acknowledge my indebtedness in the amount of \$					

Annual Inspection Certificate & Safety Standards Certificate



VEHICLE INFORMATION			
Plate#:	PP2252	Year:	2014
VIN:	1XPHDP9X2ED200960	Make:	PETERBILT
GVWR (kg):	24132	Model:	CONVENTIONAL 386
Odometer (km):	1133839	Type:	Truck

CERTIFICATE INFORMATION	
Annual Inspection Certificate	Expires at the end of: Mar 2026
Safety Standards Certificate	Expires at the end of: April 15, 2025
Vehicle Inspection Certificate Number	LS20AB74
Inspection Start Date	Mar 10, 2025 System Time: 13 : 35
Inspection End Date	Mar 10, 2025 System Time: 14 : 33

VEHICLE INSPECTION CENTRE	
Vehicle Inspection Centre #: 13563	Technician: RICHARD THOMPSON
LMB TRANSPORT INC.	
O/A LMB TRANSPORT INC.	
209 PUTMAN INDUSTRIAL RD	
BELLEVILLE, ON K8N4Z6	Technician ID: 191215
613-968-7541	STO ID/Account: 13171305
	Trade Code: 310T, 310S

I certify that I inspected this vehicle on the inspection date in accordance with the inspection procedures established by directive under s. 100.7 of the Highway Traffic Act and that the vehicle meets the required equipment and performance standards as detailed in the Vehicle Inspection Report with the above referenced Vehicle Inspection Certificate Number.

This Certificate is not a warranty on the condition of the vehicle.

Vehicle Inspection Questions?

Call the Public Contact Centre 1-833-420-2103 or go to

<https://www.ontario.ca/page/driveon-emissions-and-safety-inspection-program>.

Vehicle Inspection Certificate Number: LS20AB74

Start Date / Time: Mar 10, 2025, 1:35 PM

End Date / Time: Mar 10, 2025, 2:33 PM

VEHICLE/ENGINE INFORMATION	CHASSIS	ENGINE
Plate#: PP2252	Year: 2014	Year: 2013
VIN: 1XPHDP9X2ED200960	Make: PETERBILT	Make: CUMMINS
GVWR(kg): 24132	Model: CONVENTIONAL 386	Size (L): 13
Odometer: 1133839	Fleet ID: 167	

SAFETY INSPECTION RESULT	PASS
--------------------------	-------------

SAFETY SYSTEM INSPECTION RESULTS
All Safety System Components Passed Inspection

MANDATORY ITEMS

Inspection Item	Result	Inspection Item	Result
Axle 1, Driver Side Tire		Axle 1, Passenger Side Tire	
Tire Tread Depth (mm)	5	Tire Tread Depth (mm)	7
Initial Tire Pressure (kPa)	720	Initial Tire Pressure (kPa)	720
Disc Brakes		Disc Brakes	
Inner Friction Material Thickness (mm)	9	Inner Friction Material Thickness (mm)	9
Outer Friction Material Thickness (mm)	9	Outer Friction Material Thickness (mm)	9
Rotor Thickness (mm)	64	Rotor Thickness (mm)	64
Within OEM specifications?	Yes	Within OEM specifications?	Yes

Inspection Item	Result	Inspection Item	Result
Axle 2, Driver Side, Inner Tire		Axle 2, Passenger Side, Inner Tire	
Tire Tread Depth (mm)	13	Tire Tread Depth (mm)	12
Initial Tire Pressure (kPa)	720	Initial Tire Pressure (kPa)	720
Axle 2, Driver Side, Outer Tire		Axle 2, Passenger Side, Outer Tire	
Tire Tread Depth (mm)	13	Tire Tread Depth (mm)	12
Initial Tire Pressure (kPa)	720	Initial Tire Pressure (kPa)	720
Drum Brakes		Drum Brakes	
Bonded/riveted continuous strip		Bonded/riveted continuous strip	
Shoe Lining Thickness (mm)	Over 15	Shoe Lining Thickness (mm)	Over 15
Drum Inside Diameter (mm)	416	Drum Inside Diameter (mm)	416
Within OEM specifications?	Yes	Within OEM specifications?	Yes
S-Cam Drum Brakes		S-Cam Drum Brakes	

Chamber Type (size)	20
Brake Stroke (mm)	31

Chamber Type (size)	20
Brake Stroke (mm)	31

Inspection Item	Result
Axle 3, Driver Side, Inner Tire	
Tire Tread Depth (mm)	11
Initial Tire Pressure (kPa)	720
Axle 3, Driver Side, Outer Tire	
Tire Tread Depth (mm)	11
Initial Tire Pressure (kPa)	720
Drum Brakes	
Bonded/riveted continuous strip	
Shoe Lining Thickness (mm)	Over 15
Drum Inside Diameter (mm)	416
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	20
Brake Stroke (mm)	31

Inspection Item	Result
Axle 3, Passenger Side, Inner Tire	
Tire Tread Depth (mm)	11
Initial Tire Pressure (kPa)	720
Axle 3, Passenger Side, Outer Tire	
Tire Tread Depth (mm)	12
Initial Tire Pressure (kPa)	720
Drum Brakes	
Bonded/riveted continuous strip	
Shoe Lining Thickness (mm)	Over 15
Drum Inside Diameter (mm)	416
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	20
Brake Stroke (mm)	31

Vehicle Inspection Centre #: 13563 LMB TRANSPORT INC. 209 PUTMAN INDUSTRIAL RD BELLEVILLE, ON K8N4Z6 613-968-7541 Software Version: 2024.08.21.1	Technician #: 191215 Name: RICHARD THOMPSON Report Number: 68 Tablet ID: 2923 STO ID/Account: 13171305 Trade Code: 310T, 310S
--	---

Vehicle Inspection Questions? Call the Public Contact Centre 1-833-420-2103 or go to <https://www.ontario.ca/page/driveon-emissions-and-safety-inspection-program>