




## Annual Inspection Certificate & Safety Standards Certificate



VEHICLE INFORMATION			
Plate#:	PA73579	Year:	2015
VIN:	3HSDJAPR5FN194377	Make:	INTERNATIONAL
GVWR (kg):	52350	Model:	PROSTAR LF627 PREMIUM
Odometer (km):	1477841	Type:	Truck

CERTIFICATE INFORMATION	
Annual Inspection Certificate	Expires at the end of: Oct 2026
Safety Standards Certificate	Expires at the end of: November 6, 2025
Vehicle Inspection Certificate Number	LS20AC87
Inspection Start Date	Oct 1, 2025 System Time: 11 : 28
Inspection End Date	Oct 1, 2025 System Time: 13 : 26

VEHICLE INSPECTION CENTRE	
Vehicle Inspection Centre #: 13563	Technician: RICHARD THOMPSON
LMB TRANSPORT INC.	
O/A LMB TRANSPORT INC.	
209 PUTMAN INDUSTRIAL RD	
BELLEVILLE, ON K8N4Z6	Technician ID: 191215
613-968-7541	STO ID/Account: 13171305
	Trade Code: 310T, 310S

I certify that I inspected this vehicle on the inspection date in accordance with the inspection procedures established by directive under s. 100.7 of the Highway Traffic Act and that the vehicle meets the required equipment and performance standards as detailed in the Vehicle Inspection Report with the above referenced Vehicle Inspection Certificate Number.

This Certificate is not a warranty on the condition of the vehicle.

Vehicle Inspection Questions?  
Call the Public Contact Centre 1-833-420-2103 or go to  
<https://www.ontario.ca/page/driveon-emissions-and-safety-inspection-program>.

Vehicle Inspection Certificate Number: LS20AC87

Start Date / Time: Oct 1, 2025, 11:28 AM

End Date / Time: Oct 1, 2025, 1:26 PM

VEHICLE/ENGINE INFORMATION	CHASSIS	ENGINE
Plate#: PA73579	Year: 2015	Year: 2015
VIN: 3HSDJAPR5FN194377	Make: INTERNATIONAL	Make: CUMMINS
GVWR(kg): 52350	Model: PROSTAR LF627 PREM	Size (L):
Odometer: 1477841	Fleet ID: 172	

SAFETY INSPECTION RESULT	<b>PASS</b>
--------------------------	-------------

SAFETY SYSTEM INSPECTION RESULTS

All Safety System Components Passed Inspection
--

MANDATORY ITEMS

Inspection Item	Result
Axle 1, Driver Side Tire	
Tire Tread Depth (mm)	13
Initial Tire Pressure (kPa)	720
Drum Brakes (Limited Inspection) Bonded/riveted continuous strip	
S-Cam Drum Brakes (Limited Inspection)	

Inspection Item	Result
Axle 1, Passenger Side Tire	
Tire Tread Depth (mm)	13
Initial Tire Pressure (kPa)	720
Drum Brakes (Limited Inspection) Bonded/riveted continuous strip	
S-Cam Drum Brakes (Limited Inspection)	

Inspection Item	Result
Axle 2, Driver Side, Inner Tire	
Tire Tread Depth (mm)	8
Initial Tire Pressure (kPa)	720
Axle 2, Driver Side, Outer Tire	
Tire Tread Depth (mm)	11
Initial Tire Pressure (kPa)	720
Drum Brakes (Limited Inspection) Bonded/riveted continuous strip	
S-Cam Drum Brakes (Limited Inspection)	

Inspection Item	Result
Axle 2, Passenger Side, Inner Tire	
Tire Tread Depth (mm)	10
Initial Tire Pressure (kPa)	720
Axle 2, Passenger Side, Outer Tire	
Tire Tread Depth (mm)	9
Initial Tire Pressure (kPa)	720
Drum Brakes (Limited Inspection) Bonded/riveted continuous strip	
S-Cam Drum Brakes (Limited Inspection)	

Inspection Item	Result
Axle 3, Driver Side, Inner Tire	
Tire Tread Depth (mm)	10
Initial Tire Pressure (kPa)	720

Inspection Item	Result
Axle 3, Passenger Side, Inner Tire	
Tire Tread Depth (mm)	10
Initial Tire Pressure (kPa)	720

Axle 3, Driver Side, Outer Tire	
Tire Tread Depth (mm)	11
Initial Tire Pressure (kPa)	720
Drum Brakes (Limited Inspection) Bonded/riveted continuous strip	
S-Cam Drum Brakes (Limited Inspection)	

Axle 3, Passenger Side, Outer Tire	
Tire Tread Depth (mm)	9
Initial Tire Pressure (kPa)	720
Drum Brakes (Limited Inspection) Bonded/riveted continuous strip	
S-Cam Drum Brakes (Limited Inspection)	

Vehicle Inspection Centre #: 13563 LMB TRANSPORT INC. 209 PUTMAN INDUSTRIAL RD BELLEVILLE, ON K8N4Z6 613-968-7541 Software Version: 2025.06.18.1	Technician #: 191215 Name: RICHARD THOMPSON Report Number: 170 Tablet ID: 2923 STO ID/Account: 13171305 Trade Code: 310T, 310S
---	---

Vehicle Inspection Questions? Call the Public Contact Centre 1-833-420-2103 or go to <https://www.ontario.ca/page/driveon-emissions-and-safety-inspection-program>

LMB TRANSPORT INC.  
 209 PUTMAN RD  
 BELLEVILLE, ONTARIO K8N 4Z6  
 TEL: 613-968-7541 FAX: 613-968-7542  
 WWW.LMBTRANSPORT.COM

*[Faint handwritten notes and stamps, including a date stamp that appears to read '1/10/2025']*