Asset: - Bell B45E Articulated Dump Truck

Location:31 BURNSIDE ROAD, STAPYLTON QLD 4207

Current Tracker Hours: 7789

Current Tracker Kms: 9937

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
6839	truck wont start	02/09/2025	7704	8588	03/09/2025	Equipment breakdown	Closed	Alistair Ross
5720	Front LH indicator not working	22/05/2025	7540	7628	28/07/2025	Vaintenance	Closed	Alistair Ross
5717	Inspect and repair flashing amber light and tail lights.	22/05/2025	7540	7628	22/05/2025	To do when in workshop	Closed	Alistair Ross
5442	Reverse camera not working	30/04/2025	7539	7628	22/05/2025	Mnor defects	Closed	Alistair Ross
5391	Valve Set	24/04/2025	7538	7628	30/04/2025	Repairs	Closed	Robert Badowski Stephen Hunter
5242	Grease fault	11/04/2025	7538	7628	30/04/2025	To do when in workshop	Closed	Stephen Hunter
5101	Prestart Defect - Tracks/Tyres/Wheels Pressure, Tread and Nut	01/04/2025	7537	7583	22/04/2025	Maintenance	Closed	Alistair Ross
5083	Hydraulic Hose Blown	30/03/2025	7540	7581	22/04/2025	Equipment breakdown	Closed	Alistair Ross
5030	Annual Inspection	25/03/2025	7492	7743	21/03/2025	Annual Inspection	Closed	Stephen Hunter
5029	Brake Test	25/03/2025	7492	7743	21/03/2025	Brake Tests	Closed	Stephen Hunter
4900	7500 hours service	18/03/2025	7450	83865	22/04/2025	Routine Service	Closed	Alistair Ross Robert Badowski Stephen Hunter
4795	Tyre crack	10/03/2025	7374	82952	29/03/2025	Tyre & RimInspection	Closed	Alistair Ross Robert Badowski Stephen Hunter
4429	Prestart Defect - Flashing Light Failed	14/02/2025	7202	80988	15/02/2025	To do when in workshop	Closed	Stephen Hunter
4322	Truck won't start	10/02/2025	7171	7352	10/02/2025	Equipment breakdown	Closed	Robert Badowski
4180	Out in pos 1 side wall	29/01/2025	7093	45367	16/02/2025	Mnor defects	Closed	Stephen Hunter
4095	Defects - Left armrest	18/01/2025	7033	44538	22/04/2025	Mnor defects	Closed	Robert Badowski Alistair Ross
3937	7000 hours service	31/12/2024	6947	54835	24/03/2025	Routine Service	Closed	Stephen Hunter
3400	Fire Suppression	24/09/2024	6176	47648	17/09/2024	Fire Suppression	Closed	Operations
3403	Kestrel Brake Test	24/09/2024	6176	47650	17/09/2024	Brake Tests	Closed	Stephen Hunter
3178	Fittings & Hoses	30/08/2024			26/08/2024	Repairs	Closed	Robert Badowski
3002	6000 hours service @ 6123Hrs	09/08/2024	5940	43364	17/09/2024	Routine Service	Closed	Alistair Ross
2648	Msc Parts Invoice	09/07/2024	5552	38690	09/07/2024	Repairs	Closed	Operations
2597	5500 hours service @ 5677Hrs	30/06/2024	5445	37680	02/08/2024	Routine Service	Closed	Alistair Ross
2172	5000 hr service @ 4985hrs	04/05/2024	4945	32186	21/05/2024	Routine Service	Closed	Shane Currie
1961	4500 hours service	13/03/2024	4444	25991	19/04/2024	Routine Service	Closed	Dylan Williams
1779	4000 hours service	15/01/2024	3957	21302	07/02/2024	Routine Service	Closed	Dylan Williams
1680	3500 hours service	26/11/2023	3451	15351	26/06/2024	Routine Service	Closed	Operations

Werk Order	Besleppfish level sensor	67/e1a1/202 3	Created Hours	Created Km	626A16A64ed	Mainten ance	Respstatus	Aଞ୍ଜୀଖିନ୍ୟି To/Completed By
1548	3000 hours service	26/10/2023	2947	8565	06/11/2023	Routine Service	Closed	
1528	Fire Suppression Related Costs	25/10/2023	2927	8299	12/03/2024	Maintenance	Closed	Chubb Fire Tech
1501	Hitachi - Leaf Springs	24/10/2023	2910	8063	23/10/2023	Maintenance	Closed	Operations
1487	TYRE RELATED COSTS	24/10/2023	2910	8063	29/12/2023	Maintenance	Closed	Operations
1406	Htachi - Filter & Pump	11/10/2023	2710	5317	06/10/2023	Maintenance	Closed	Operations
1274	2500 hours service - 2494hrs	14/09/2023	2440	1538	27/09/2023	Routine Service	Closed	Operations
1225	Kestrel Brake Test	04/09/2023	1000	0	03/09/2023	Routine Service	Closed	Alistair Ross
971	1000hr Service	22/06/2023	500	0	21/06/2023	Routine Service	Closed	Alistair Ross
926	Kestrel Brake Test	29/05/2023	500	0	23/03/2023	Routine Service	Closed	Alistair Ross
883	500hr Service - 500hrs - Tyre Report	15/05/2023	0	0	07/05/2023	Routine Service	Closed	Robert Badowski