

03862367

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspection
Box 45064 Regent Postal Centre
Winnipeg, MB, R2C 5C7
1-204-985-0920Manitoba
A810630

Date Inspection Started DAY: 28 MO: 03 YR: 24	Station Number A63104	Station Name LGL Truck & Trailer Ltd	City Winnipeg
Date Inspection Completed DAY: 03 MO: 04 YR: 24	Mechanic Number M013913	Mechanic Signature <i>[Signature]</i>	Station Phone Number 673-2645
Inspection Expiry Date DAY: 30 MO: 04 YR: 25	Vehicle Owner Calidon Financial Services INC - Calvin R Mispelon		
	Address Box 491, Reston, MB, R0M 1X0		
	Phone [Blank]		
<input checked="" type="checkbox"/> Pass/Safe Vehicle <input checked="" type="checkbox"/> Fail/Unsafe Vehicle <input type="checkbox"/> Fail/Hazardous	Licence Number LEJ416H	Prov. MB	NSC # MB2119869
	Vehicle Identification Number 5K3R1A1L1D112FP161R136105	Make Wester	Model [Blank]
	Confirmed legible Vehicle Identification Number on vehicle <input type="checkbox"/>	Odometer Reading 497146	Odom. Type km
		Year 2015	Unit # [Blank]

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

___ Truck 331112 KGS ☒ Truck Tractor ___ Trailer ___ Semi-Trailer ___ Bus ___ School Bus ___ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																																																											
<input checked="" type="checkbox"/>		Section 1 - Power Train: Defects (if any)																																																																																																											
<input checked="" type="checkbox"/>		Section 2 Suspension: Defects (if any)																																																																																																											
<input checked="" type="checkbox"/>		Section 3 - Brake Systems: 3H <u>3A</u> Defects (if any) Circle Brake Type																																																																																																											
		Brake Inspection Type: <u>A</u> B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																																																											
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>9/16</td> <td>5/8</td> <td>16.590</td> <td>16.595</td> <td>1.5"</td> <td>1.5"</td> </tr> <tr> <td>2</td> <td>1 1/16</td> <td>1 1/16</td> <td>16.600</td> <td>16.600</td> <td>1.5"</td> <td>1.5"</td> </tr> <tr> <td>3</td> <td>3/4</td> <td>3/4</td> <td>16.590</td> <td>16.595</td> <td>1.5"</td> <td>1.5"</td> </tr> <tr> <td>4</td> <td>5/8</td> <td>5/8</td> <td>16.595</td> <td>16.590</td> <td>1.5"</td> <td>1.5"</td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	9/16	5/8	16.590	16.595	1.5"	1.5"	2	1 1/16	1 1/16	16.600	16.600	1.5"	1.5"	3	3/4	3/4	16.590	16.595	1.5"	1.5"	4	5/8	5/8	16.595	16.590	1.5"	1.5"	5							Final Measurement																																																										
Axle	Lining			Drum/Rotor		Stroke																																																																																																							
	L	R	L	R	L	R																																																																																																							
1	9/16	5/8	16.590	16.595	1.5"	1.5"																																																																																																							
2	1 1/16	1 1/16	16.600	16.600	1.5"	1.5"																																																																																																							
3	3/4	3/4	16.590	16.595	1.5"	1.5"																																																																																																							
4	5/8	5/8	16.595	16.590	1.5"	1.5"																																																																																																							
5																																																																																																													
Final Measurement																																																																																																													
<input checked="" type="checkbox"/>		Section 4 - Steering: Defects (if any)																																																																																																											
<input checked="" type="checkbox"/>		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																																																											
<input checked="" type="checkbox"/>		Section 6 - Lamps: Defects (if any)																																																																																																											
<input checked="" type="checkbox"/>		Section 7 - Electrical System: Defects (if any)																																																																																																											
<input checked="" type="checkbox"/>		Section 8 - Body: Defects (if any)																																																																																																											
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Section 9 - Tire & Wheel: Defects (if any) <u>4A - installation pressure 5C - steer axle wheel seal leaking</u>																																																																																																											
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="6">Tread Depth mm</th> <th colspan="6">Air Pressure</th> </tr> <tr> <th colspan="3">Initial</th> <th colspan="3">Corrected</th> <th colspan="3">Initial</th> <th colspan="3">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th></th> <th>L</th> <th>R</th> <th></th> <th>L</th> <th>R</th> <th></th> <th>L</th> <th>R</th> <th></th> </tr> </thead> <tbody> <tr> <td>1</td> <td></td> <td>7</td> <td>10</td> <td></td> <td></td> <td></td> <td></td> <td>90</td> <td>90</td> <td></td> <td></td> <td>105</td> <td>105</td> </tr> <tr> <td>2</td> <td>21</td> <td>21</td> <td>21</td> <td>21</td> <td></td> <td></td> <td></td> <td>85</td> <td>85</td> <td>85</td> <td>85</td> <td>105</td> <td>105</td> </tr> <tr> <td>3</td> <td>21</td> <td>21</td> <td>21</td> <td>21</td> <td></td> <td></td> <td></td> <td>85</td> <td>85</td> <td>85</td> <td>85</td> <td>105</td> <td>105</td> </tr> <tr> <td>4</td> <td>21</td> <td>21</td> <td>21</td> <td>21</td> <td></td> <td></td> <td></td> <td>85</td> <td>85</td> <td>85</td> <td>85</td> <td>105</td> <td>105</td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth mm						Air Pressure						Initial			Corrected			Initial			Corrected			L	R		L	R		L	R		L	R		1		7	10					90	90			105	105	2	21	21	21	21				85	85	85	85	105	105	3	21	21	21	21				85	85	85	85	105	105	4	21	21	21	21				85	85	85	85	105	105	5													
Axle	Tread Depth mm						Air Pressure																																																																																																						
	Initial			Corrected			Initial			Corrected																																																																																																			
	L	R		L	R		L	R		L	R																																																																																																		
1		7	10					90	90			105	105																																																																																																
2	21	21	21	21				85	85	85	85	105	105																																																																																																
3	21	21	21	21				85	85	85	85	105	105																																																																																																
4	21	21	21	21				85	85	85	85	105	105																																																																																																
5																																																																																																													
<input checked="" type="checkbox"/>		Section 10 - Coupling Devices: Defects (if any)																																																																																																											

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date: