

03928070

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspections
Box 45084 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0070

Manitoba

A908723

Date Inspection Started DAY: 03 MO: 01 YR: 25	Station Number A11370	Station Name Barry's Truck & Trailer Rep.	City Winnipeg	Station Phone Number 204-638-6334
Date Inspection Completed DAY: 10 MO: 01 YR: 25	Mechanic Number M918415	Mechanic Signature [Signature]	Vehicle Owner Pinner Bros Logging Ltd	Phone A01010
Inspection Expiry Date DAY: 31 MO: 01 YR: 26	Vehicle Identification Number 1XKDD39X66A990988	Province MB	Postal Code R2C 5C7	Unit #
☒ Pass/Safe Vehicle ☒ Fail/Unsafe Vehicle ☐ Fail/Hazardous	License Number 4H6G 115	Prev. Reg. # [Blank]	NSC # [Blank]	Odometer Reading 870834
	Vehicle Identification Number 1XKDD39X66A990988	State KV	Model T80	Year 06

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ KCB ☒ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

P	R	Mark 'X' under 'R' when item Rejected 'X' under 'R' when item Hazardous 'X' under 'P' when item Corrected or No Defects found in Section
Y	X	Section 1 - Power Train: Defects (if any) <u>Replace muffler & down stream restrictor</u>
Y	Y	Section 2 Suspension: Defects (if any) <u>Replace 3 rear shock absorbers</u> <u>Repair loose suspension</u>
Y	Y	Section 3 - Brake Systems: 3H (3A) Defects (if any) <u>ABS sensor has</u> <u>ABS solenoid valve seal leaking</u> <u>13 Brake master air fork stream</u> <u>+ leaking air tank - bleed through</u> <u>15 Replace 1st brake shoes cracked</u> <u>16 Replace Chassis pin PS rear lower</u>
Y	Y	Section 4 - Steering: Defects (if any)
Y	Y	Section 5 - Instruments & Auxiliary Equipment: Defects (if any) <u>Replace heater control valve</u>
Y	Y	Section 6 - Lamps: Defects (if any) <u>Repair 1st tail + brake light + wiring</u>
X		Section 7 - Electrical System: Defects (if any)
Y	Y	Section 8 - Body: Defects (if any) <u>Replace 1st pipe PS rear</u> <u>1st pipe missing replace minus - loose crown nuts bolt</u> <u>Repair PS lower leg</u>
Y	Y	Section 9 - Tire & Wheel: Defects (if any) <u>1st Air Tire Pressure</u>
Y	Y	Section 10 - Coupling Devices: Defects (if any) <u>1st Air Tire Pressure</u>

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
1	L	R	L	R	L	R	L	R
1	20	20			85	90	105	105
2	23	24	24	24	82	81	82	88
3	24	24	24	24	85	76	85	88
4								
5								

THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

A01-16

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date: