



Fire Alarm System

Annual Test And Inspection Report
Semi Annual Test And Inspection Report
Verification Report

Building Name:
Address: 360 Chaplin St W
Swift Current, SK

Inspection Date: May 13, 2026
Due Date: May 13, 2027

Panel Location: N/A
Telephone #: 306-539-8159
Person Contacted: Andrea

**System
Manufacturer:
Model No:**

Single Stage
 Two Stage

Summary of Results: (Every line must have the appropriate markings in the space provided)

- Yes** **No**
- The Fire Alarm System is fully functional, with no deficiencies
- The Fire Alarm System is operational with minor deficiencies as noted on the pages attached.
- The Fire Alarm System had major deficiencies as noted on the pages attached.
- This is to certify that the Fire Alarm System has been tested and inspected in accordance with the standards for the inspection and testing of Fire Alarm Systems, CAN/ULC-S536-97, and these records document the results of testing performed.
- A copy of the report will be given to: Andrea andreaklip@gmail.com

Who is the owner Or owner's representative For the building

Name of Technician Conducting Test: Tyler Jones
CFAA Technician No: 22-997968
Technician Signature:

Technicians Pre-test Checklist

- Alert the management of the building that the fire alarm system is being tested and that alternate measures under the fire safety plan should be implemented.
- Has an alternate plan been established to alert occupants and local Fire Department should an actual fire condition occur during testing?
- If there is a remote connection to a central monitoring station or Fire Department, take necessary steps to properly alert the central monitoring station or the Fire Department.

Melhoff Electric Ltd

1060 Chaplin St. W. Swift Current, Sk. S9H 0G6
Ph. (306) 773-8368 Fax (306) 773-7147

**Fire Alarm
Inspection
Report**



Yes No N/A

The system is monitored by a Central Station.

Monitoring Company

Telephone No:

Was the Monitoring Company Notified?

Have the building occupants been made aware of the Fire Alarm Testing?

Has a pre-determined time been established for testing signaling devices?

Have provisions been made for acquiring access to the secured areas of the building?

Are there spare reset and panel keys available?

The Fire Alarm System has all the required documentation?

Comments: FA breaker painted red and lock installed on breaker.
Breaker panel located in West Center Hallway.

