www.girardgraderhire.com
accounts@girardgraderhire.com.au
0267526462
01/11/2023 - 06/11/2026

Comprehensive Plant Management
https://aquipa.com

Upload Maintenance Form - 2348M60

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	30/07/2026
Date submitted:	30/07/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Multipac
Model	VP2100
Type	Roller - Multi-Tyred
VIN / Serial	LGH6524ECPR061123
Registration	51808E
Plant Internal ID	51808E
Aquipa Plant ID	2348M60



Maintenance Upload Details	
Maintenance Description:	Serviced at 2130hrs Next service at 2380hrs Submitted By Scott Peters - 30/07/2026 12:10 pm
Upload Files:	Basic Service Checklist.docx Submitted By Scott Peters - 30/07/2026 12:10 pm

Upload Maintenance Form - 2348M60

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	10/07/2026
Date submitted:	14/07/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Multipac
Model	VP2100
Type	Roller - Multi-Tyred
VIN / Serial	LGH6524ECPR061123
Registration	51808E
Plant Internal ID	51808E
Aquipa Plant ID	2348M60



Maintenance Upload Details	
Maintenance Description:	fit supplied windscreen Submitted By Scott Girard - 14/07/2026 10:32 am
Upload Files:	

Upload Maintenance Form - 2348M60

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	16/06/2026
Date submitted:	17/06/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Multipac
Model	VP2100
Type	Roller - Multi-Tyred
VIN / Serial	LGH6524ECPR061123
Registration	51808E
Plant Internal ID	51808E
Aquipa Plant ID	2348M60



Maintenance Upload Details	
Maintenance Description:	Replaced damaged hyd hose Travelled to machine Submitted By Scott Peters - 17/06/2026 02:00 pm
Upload Files:	

Upload Maintenance Form - 2348M60

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	25/03/2026
Date submitted:	26/03/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Multipac
Model	VP2100
Type	Roller - Multi-Tyred
VIN / Serial	LGH6524ECPR061123
Registration	51808E
Plant Internal ID	51808E
Aquipa Plant ID	2348M60



Maintenance Upload Details	
Maintenance Description:	Serviced at 1820hrs 1100hra for next service Submitted By Scott Peters - 26/03/2026 02:42 pm
Upload Files:	Basic Service Checklist.docx Submitted By Scott Peters - 26/03/2026 02:42 pm

Upload Maintenance Form - 2348M60

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	05/03/2026
Date submitted:	19/03/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Multipac
Model	VP2100
Type	Roller - Multi-Tyred
VIN / Serial	LGH6524ECPR061123
Registration	51808E
Plant Internal ID	51808E
Aquipa Plant ID	2348M60



Maintenance Upload Details	
Maintenance Description:	inspect machine for ac system blowing hot air found hose under cab to be leaking remove hose and make new hose fit new hose add 1.8kg of refrigerant to system Harborne auto - inv 1481 Submitted By Scott Girard - 19/03/2026 03:49 pm
Upload Files:	

Upload Maintenance Form - 2348M60

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	22/12/2025
Date submitted:	22/12/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Multipac
Model	VP2100
Type	Roller - Multi-Tyred
VIN / Serial	LGH6524ECPR061123
Registration	51808E
Plant Internal ID	51808E
Aquipa Plant ID	2348M60



Maintenance Upload Details	
Maintenance Description:	Basic service at 1598hrs Next service at 1850hrs Submitted By Scott Peters - 22/12/2025 10:15 am
Upload Files:	Basic Service Checklist.docx

Upload Maintenance Form - 2348M60

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	01/10/2025
Date submitted:	01/10/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Multipac
Model	VP2100
Type	Roller - Multi-Tyred
VIN / Serial	LGH6524ECPR061123
Registration	51808E
Plant Internal ID	51808E
Aquipa Plant ID	2348M60



Maintenance Upload Details	
Maintenance Description:	Serviced at 1305hrs Next service at 1555hrs Submitted By Scott Peters - 01/10/2025 09:55 am
Upload Files:	Basic Service Checklist.docx

Upload Maintenance Form - 2348M60

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	26/05/2025
Date submitted:	27/05/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Multipac
Model	VP2100
Type	Roller - Multi-Tyred
VIN / Serial	LGH6524ECPR061123
Registration	51808E
Plant Internal ID	51808E
Aquipa Plant ID	2348M60



Maintenance Upload Details	
Maintenance Description:	inspect roller for AC not operating correctly connect gauges and found system pressure to be low inspect for leaks and found loose fitting under cab, tighten fitting add 300g of R134A, test operation ok Submitted By Scott Girard - 27/05/2025 11:44 am
Upload Files:	

Upload Maintenance Form - 2348M60

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	19/02/2025
Date submitted:	13/03/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Multipac
Model	VP2100
Type	Roller - Multi-Tyred
VIN / Serial	LGH6524ECPR061123
Registration	51808E
Plant Internal ID	51808E
Aquipa Plant ID	2348M60



Maintenance Upload Details	
Maintenance Description:	AC System not operating correctly connect gauges, found machine to be low on refrigerant add 88g of refrigerant to system check for leaks, none found INV- 0320 Harborne auto electrical &air Submitted By Scott Girard - 13/03/2025 01:33 pm
Upload Files:	

Upload Maintenance Form - 2348M60

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	31/01/2025
Date submitted:	31/01/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Multipac
Model	VP2100
Type	Roller - Multi-Tyred
VIN / Serial	LGH6524ECPR061123
Registration	51808E
Plant Internal ID	51808E
Aquipa Plant ID	2348M60



Details	
Maintenance Description:	Cut old glass away from frame. Fitted plastic back windscreen. Waiting on new glass one to show up Submitted By Scott Peters - 31/01/2025 06:46 pm
Upload Files:	

Upload Maintenance Form - 2348M60

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	22/01/2025
Date submitted:	22/01/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Multipac
Model	VP2100
Type	Roller - Multi-Tyred
VIN / Serial	LGH6524ECPR061123
Registration	51808E
Plant Internal ID	51808E
Aquipa Plant ID	2348M60



Details	
Maintenance Description:	Serviced at 1108hrs 1350hrs Submitted By Scott Peters - 22/01/2025 12:23 pm
Upload Files:	Basic Service Checklist.docx

Upload Maintenance Form - 2348M60

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	06/11/2024
Date submitted:	06/11/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Multipac
Model	VP2100
Type	Roller - Multi-Tyred
VIN / Serial	LGH6524ECPR061123
Registration	51808E
Plant Internal ID	51808E
Aquipa Plant ID	2348M60



Details	
Maintenance Description:	Travelled to machine. Removed radiator cover. Blew out for half hour Topped coolant back up and ran machine for 20mins. Didn't find any leaks Keep an eye on Submitted By Scott Peters - 06/11/2024 09:17 pm
Upload Files:	

Upload Maintenance Form - 2348M60

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	19/10/2024
Date submitted:	21/10/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Multipac
Model	VP2100
Type	Roller - Multi-Tyred
VIN / Serial	LGH6524ECPR061123
Registration	51808E
Plant Internal ID	51808E
Aquipa Plant ID	2348M60



Details	
Maintenance Description:	Inspect Multipac Roller for A/C not functioning correctly Connect gauges, found system to be low on refrigerant Inspect for any leaks in system, all ok Could not identify any leaks Add 700g of refrigerant to system and check operation, all ok *Monitor system for suspected evaporator leak Submitted By Scott Girard - 21/10/2024 12:58 pm
Upload Files:	Invoice INV-0123.pdf Submitted By Scott Girard - 21/10/2024 12:58 pm

Upload Maintenance Form - 2348M60

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	22/08/2024
Date submitted:	22/08/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Multipac
Model	VP2100
Type	Roller - Multi-Tyred
VIN / Serial	LGH6524ECPR061123
Registration	51808E
Plant Internal ID	51808E
Aquipa Plant ID	2348M60



Details	
Maintenance Description:	800hr service NS:1000hrs Submitted By Scott Peters - 22/08/2024 02:16 pm
Upload Files:	Basic Service Checklist.docx

Upload Maintenance Form - 2348M60

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	23/04/2024
Date submitted:	23/04/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Multipac
Model	VP2100
Type	Roller - Multi-Tyred
VIN / Serial	LGH6524ECPR061123
Registration	51808E
Plant Internal ID	51808E
Aquipa Plant ID	2348M60



Details	
Maintenance Description:	Basic service 400hr NS 650hrs Submitted By Scott Peters - 23/04/2024 01:48 pm
Upload Files:	Basic Service Checklist.docx

Basic Maintenance Form - 2348M60

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	25/01/2024
Date submitted:	25/01/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Multipac
Model	VP2100
Type	Roller - Multi-Tyred
VIN / Serial	LGH6524ECPR061123
Registration	51808E
Plant Internal ID	51808E
Aquipa Plant ID	2348M60



Usage Log	
Total Hours	178 Submitted By Scott Peters - 25/01/2024 12:18 pm

Details	
Maintenance Performed Date:	25/01/2024 Submitted By Scott Peters - 25/01/2024 12:19 pm
Maintenance Description:	Basic service Next service 300hrs Submitted By Scott Peters - 25/01/2024 12:19 pm
Upload Files:	Basic Service Checklist.docx