

www.girardgraderhire.com
accounts@girardgraderhire.com.au
0267526462
01/11/2023 - 06/11/2026



Comprehensive Plant Management
https://aquipa.com

Upload Maintenance Form - 2348M98

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	15/09/2026
Date submitted:	22/09/2026

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Lusty	
Model	Dolly	
Type		
VIN / Serial	6F8T250000LE06976	
Registration	YN88HN	
Plant Internal ID	YN88HN	
Aquipa Plant ID	2348M98	

Maintenance Upload Details	
Maintenance Description:	Labour Inspect Failure, brake calipers come loose No way of repair on roadside Carry out following to get truck and trailers off road Lift axles and remove wheels Remove calipers, cap booster hoses Refit wheels Submitted By Scott Girard - 22/09/2026 09:50 am
Upload Files:	invoice-8170.pdf Submitted By Scott Girard - 22/09/2026 09:50 am

Upload Maintenance Form - 2348M98

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	24/08/2026
Date submitted:	24/08/2026

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Lusty	
Model	Dolly	
Type		
VIN / Serial	6F8T250000LE06976	
Registration	YN88HN	
Plant Internal ID	YN88HN	
Aquipa Plant ID	2348M98	

Maintenance Upload Details	
Maintenance Description:	Replaced driver side drawbar bushes Submitted By Scott Peters - 24/08/2026 02:40 pm
Upload Files:	

Upload Maintenance Form - 2348M98

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	24/08/2026
Date submitted:	24/08/2026

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Lusty	
Model	Dolly	
Type		
VIN / Serial	6F8T250000LE06976	
Registration	YN88HN	
Plant Internal ID	YN88HN	
Aquipa Plant ID	2348M98	

Maintenance Upload Details	
Maintenance Description:	Welded cracks in frame work. Welded hand rail back on Replaced every wheel bearing and brake pads. Replaced front right hub and rotor. Replaced reflecting sign on rear mud guards Submitted By Scott Peters - 24/08/2026 01:49 pm
Upload Files:	

Upload Maintenance Form - 2348M98

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	02/12/2025
Date submitted:	02/12/2025

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Lusty	
Model	Dolly	
Type		
VIN / Serial	6F8T250000LE06976	
Registration	YN88HN	
Plant Internal ID	YN88HN	
Aquipa Plant ID	2348M98	

Maintenance Upload Details	
Maintenance Description:	Replaced second axle rh side brake booster. Submitted By Scott Peters - 02/12/2025 02:10 pm
Upload Files:	