www.girardgraderhire.com
accounts@girardgraderhire.com.au
0267526462
01/11/2023 - 06/11/2026

Comprehensive Plant Management
https://aquipa.com

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	26/08/2026
Date submitted:	03/09/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Replacement of 1x tyres Invoice_345280 Submitted By Scott Girard - 03/09/2026 11:19 am
Upload Files:	Invoice345280.pdf Submitted By Scott Girard - 03/09/2026 11:19 am

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	25/08/2026
Date submitted:	02/09/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Invoice 345243 2 x new tyres - Submitted By Scott Girard - 02/09/2026 09:16 am
Upload Files:	Invoice345243.pdf Submitted By Scott Girard - 02/09/2026 09:16 am

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	16/07/2026
Date submitted:	19/08/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Bring truck into the workshop and lift hoist carry out clutch adjustment to achieve 1/2 inch gap remove grease nipple on the throw-out bearing, install nipple and make grease hose for the bearing, mount the grease line along the front left mudguard repair an air leak on the governor line from compressor to the air-dryer repair hose on the 2nd axle brake booster joiner hose inspect truck for more faults, found the air bags leaking, and the drive tyres needing replacement multiple oil leaks coming from the engine The gearstick needs replacing as the air is leaking past the air fittings drop the truck off to hardmans for windscreen replacement Submitted By Scott Girard - 19/08/2026 09:51 am
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	10/08/2026
Date submitted:	12/08/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Replaced front right air bag. Removed and replaced drivers side door glass and regulator One more air bag to do Submitted By Scott Peters - 12/08/2026 08:03 am
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	06/08/2026
Date submitted:	06/08/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Replaced brake pressure sensor in foot pedal. As old one had broken terminal Submitted By Scott Peters - 06/08/2026 03:55 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	04/08/2026
Date submitted:	04/08/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Replaced broken clearance light. Replaced leaking supply hose to dryer Submitted By Scott Peters - 04/08/2026 05:13 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	04/08/2026
Date submitted:	04/08/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Serviced at 606054kms Next 626,000kms Replaced front left air bag Replaced rear right air bag Fixed roof liner Welded up bumper bar backet Glued in number plate light. Tightened up mud guards Submitted By Scott Peters - 04/08/2026 12:02 pm
Upload Files:	Basic Service Checklist.docx Submitted By Scott Peters - 04/08/2026 12:02 pm

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	26/06/2026
Date submitted:	30/06/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Replaced left rear taillight on truck Replaced air fitting on brakes Submitted By Scott Peters - 30/06/2026 10:41 am
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	23/06/2026
Date submitted:	23/06/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Replaced and Rewired left rear tail light Submitted By Scott Peters - 23/06/2026 08:10 am
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	12/06/2026
Date submitted:	16/06/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	1 x haulmax 11R22.5 jukes and son inv - 342126 Submitted By Scott Girard - 16/06/2026 10:24 am
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	15/06/2026
Date submitted:	15/06/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Serviced at 584748kms Next service at 605,000kms Submitted By Scott Peters - 15/06/2026 08:17 am
Upload Files:	Basic Service Checklist.docx Submitted By Scott Peters - 15/06/2026 08:17 am

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	26/05/2026
Date submitted:	02/06/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	remove rocker cover and inspect cam, found 2 jake rockers and 1 exhaust rocker rollers damaged. also found cam housing leaking so removed cam housing. remove rocker shafts and cam shafts. found exhaust cam U/S. replace parts and refit cam housing. carry out valve set. bleed fuel system and start engine. carry out test drive. all okay Submitted By Scott Girard - 02/06/2026 01:01 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	03/03/2026
Date submitted:	26/03/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	1 bridgestone 1 maxi balance beads 1 bridgestone17.5 1 fiiting earthmoving above 1 myers 1 bridgestone 1 myers 1 fitting earth moving under Submitted By Scott Girard - 26/03/2026 03:14 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	16/03/2026
Date submitted:	26/03/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	1 puncture tyre Submitted By Scott Girard - 26/03/2026 03:08 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	20/03/2026
Date submitted:	26/03/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	1 vortex 11R22.5 Submitted By Scott Girard - 26/03/2026 03:07 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	05/03/2026
Date submitted:	26/03/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	adjust head lights on truck clean out radiator and condenser diagnose ice pack not starting and screen showing fault code check oil level clean air filter found code too be related to service number Submitted By Scott Girard - 26/03/2026 02:58 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	16/03/2026
Date submitted:	19/03/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	puncture tyre jukes and sons - inv 338121 Submitted By Scott Girard - 19/03/2026 03:58 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	05/03/2026
Date submitted:	19/03/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	adjust head light on truck clean out radiator and condenser diagnose ice pack not starting and screen showing fault code clean air filter Submitted By Scott Girard - 19/03/2026 03:47 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	14/03/2026
Date submitted:	19/03/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	for worked completed on front end to improve handling control and complying and exceeding Australian standards 2670-1990 and in accordance with iso 2631-1 1985 for light and heavy commercial vehicles Submitted By Scott Girard - 19/03/2026 03:45 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	03/02/2026
Date submitted:	18/02/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	inspect truck for no start found batteries to be flat found battery terminal and bolt to be loose which was giving the battery a poor change tighten everything up Submitted By Scott Girard - 18/02/2026 02:32 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	07/02/2026
Date submitted:	18/02/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	remove broken bolts from ac compressor and alternator bracklet and fit new bolts Submitted By Scott Girard - 18/02/2026 02:27 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	05/02/2026
Date submitted:	18/02/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Diagnose why ice pack wont work started ice pack notice it wqsnt getting cold, so removede ice pack cover and noticed that the compression and alternator bracket had broken bolts Submitted By Scott Girard - 18/02/2026 02:26 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	16/02/2026
Date submitted:	16/02/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Serviced at 560,000kms Next service at 580,000kms Submitted By Scott Peters - 16/02/2026 12:21 pm
Upload Files:	Basic Service Checklist.docx Submitted By Scott Peters - 16/02/2026 12:21 pm

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	11/02/2026
Date submitted:	12/02/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	inspect truck for no start found batteries to be flat found battery terminal and bolt to be loose which was giving battery a poor change tighten everything up Submitted By Scott Girard - 12/02/2026 02:07 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	26/01/2026
Date submitted:	02/02/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Blow out heater core refit previously removed components Evacuate system Charge system with 1.6kg of refrigerant Submitted By Scott Girard - 02/02/2026 02:17 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	16/01/2026
Date submitted:	02/02/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Diagnose air conditioning not working connect gauges Add 1500g of refrigerant to system inspect system for leaks found hose from compressor to condenser to have a leak and requires replacing Submitted By Scott Girard - 02/02/2026 02:14 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	20/01/2026
Date submitted:	22/01/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	inspect truck for icepack issue- low preessure faults and engine fan faults remove cover check oil inspect engine fan and test for power , no power unplug fan and test operation found fan to have short ground order replacement fan connect gauges found system to be low on refrigerant add 800g of refrigerant to system Submitted By Scott Girard - 22/01/2026 12:54 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	08/01/2026
Date submitted:	09/01/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Repaired broken wires for tail lights Submitted By Scott Peters - 09/01/2026 10:32 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	07/11/2025
Date submitted:	11/11/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	service on icepack drain and replace engine oil remove and clean air filters run ice pack connect ac gauges and check system pressures Submitted By Scott Girard - 11/11/2025 11:07 am
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	04/10/2025
Date submitted:	11/11/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	remove and replace engine oil and filter remove and replace air filter remove and replace fuel filter blow out radiator prime fuel system inspect auto greaser for not functioning found bad connection inside pump housing disassemble pump repair wiring reassemble pump and test operation, all ok secure wiring on all filters Submitted By Scott Girard - 11/11/2025 10:49 am
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	05/10/2025
Date submitted:	11/11/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	ac not working correctly found ac hose from compressor to tx valve to be spilt and requires replacement Submitted By Scott Girard - 11/11/2025 10:45 am
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	07/11/2025
Date submitted:	11/11/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	service on ice pack drain and replace engine oil remove and clean air filters run ice pack connect ac gauges check system pressures Submitted By Scott Girard - 11/11/2025 10:39 am
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	29/09/2025
Date submitted:	11/11/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	8 haulmax tyres Submitted By Scott Girard - 11/11/2025 10:22 am
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	28/10/2025
Date submitted:	11/11/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	2 x BF goodrich 385/65R22.5 2 x Sundry 18oz Submitted By Scott Girard - 11/11/2025 10:12 am
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	28/07/2025
Date submitted:	28/07/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Serviced at 520500kms Next service at 540,000kms Made fuel primer pump set up to suit Submitted By Scott Peters - 28/07/2025 02:23 pm
Upload Files:	Basic Service Checklist.docx

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	13/06/2025
Date submitted:	17/06/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	remove left hand rear tyres and back the hand brake off to remove the brake drum remove wheel speed sensor unplug harness and pull wiring through backing plate clean housing fit new sensor and set clearance refit harness refit brake drum and tyre Submitted By Scott Girard - 17/06/2025 09:08 am
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	16/06/2025
Date submitted:	16/06/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Remove water tank holder Re weld and make stronger Submitted By Scott Peters - 16/06/2025 02:14 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	10/06/2025
Date submitted:	10/06/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Replaced all batteries due to truck not starting Replaced hyd fitting seals Replaced injector seals Tightened up coolant hose Replaced Abs sensor rear left Submitted By Scott Peters - 10/06/2025 02:39 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	12/05/2025
Date submitted:	13/05/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Replaced cab ride height valve and linkage Submitted By Scott Peters - 13/05/2025 07:18 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	28/04/2025
Date submitted:	28/04/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Fitted new tail light and Rewired Removed old front blinker and replaced with new ones and Rewired up Got clearance lights working as well Submitted By Scott Peters - 28/04/2025 12:39 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	04/04/2025
Date submitted:	04/04/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Replaced front left hand head light and Rewired blinker Replaced 4 rear mud guards Submitted By Scott Peters - 04/04/2025 11:45 am
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	26/03/2025
Date submitted:	27/03/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	diagnose ABS light on dash found to be left rear wheel speed sensor check all wheel speed sensor harnesses, all ok remove rear cover from truck to allow access to the rear wheel speed sensor harness check right side harness, all ok refit cover connect DDL and inspect vehicle for fault codes vehicle produced fault code wheel speed sensor Axle 2 left data valid but below normal operating range POS78 tyres will need to be removed so wheel speed sensor can be replaced when truck is available Submitted By Scott Girard - 27/03/2025 10:05 am
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	13/03/2025
Date submitted:	13/03/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Maintenance Upload Details	
Maintenance Description:	Heavy truck alignment steer and drive beeline Completed by Moree Tyrepower - INV1196297 Submitted By Scott Girard - 13/03/2025 11:19 am
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	28/02/2025
Date submitted:	28/02/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Details	
Maintenance Description:	500287kms Replaced Horton fan clutch and bearings Submitted By Scott Peters - 28/02/2025 09:58 am
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	20/02/2025
Date submitted:	26/02/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Details	
Maintenance Description:	Replaced tyres 2x Yokohama 385/65R22.5 158L tyres supplied and fitted by Jukes & Sons Tyre Centre Moree Submitted By Scott Girard - 26/02/2025 11:23 am
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	21/02/2025
Date submitted:	21/02/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Details	
Maintenance Description:	Serviced at 499954kms Next at 520,000kms Submitted By Scott Peters - 21/02/2025 12:35 pm
Upload Files:	Basic Service Checklist.docx

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	10/02/2025
Date submitted:	10/02/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Details	
Maintenance Description:	497,500kms Replaced front springs,shocks Replaced rear shocks Replaced back left wheel seal, brakes, brake drum Replaced front cab mounts Submitted By Scott Peters - 10/02/2025 03:25 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	06/02/2025
Date submitted:	10/02/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Details	
Maintenance Description:	Inspect for indicator fuse blowing due to short to ground Found short to be from cab bulkhead harness to centre chassis connector, run overland wire to repair. test OK Materials and labour supplied by Harborne Auto Electrical & AC Pty Ltd - INV-0287 Submitted By Scott Girard - 10/02/2025 11:11 am
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	04/02/2025
Date submitted:	05/02/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Details	
Maintenance Description:	Fitted repaired intake pipe Topped up transmission oil Fitted new oil cooler and pipe Refitted bumper bar Submitted By Scott Peters - 05/02/2025 12:37 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	28/01/2025
Date submitted:	28/01/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Details	
Maintenance Description:	Rewired up new headlight Submitted By Scott Peters - 28/01/2025 12:30 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	19/01/2025
Date submitted:	21/01/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Details	
Maintenance Description:	Inspect truck for AC system not functioning correctly - Found system to have faulty compressor, replaced compressor, receiver drier, TX valve & evaporator - Charge system with 1.8kg Labour and materials supplied by Harborne Auto Electrical & AC Pty Ltd (INV-0261) Submitted By Scott Girard - 21/01/2025 05:04 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	15/12/2024
Date submitted:	17/12/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Details	
Maintenance Description:	Inspect A/C system on Western Star for not functioning correctly (blowing hot air) Connect gauges, found system to be low on refrigerant Inspect for leaks, found freon to be leaking from evaporator discharge pipe at firewall Advise customer that evaporator coil will require replacement Submitted By Scott Girard - 17/12/2024 03:08 pm
Upload Files:	Invoice INV-0226.pdf Submitted By Scott Girard - 17/12/2024 03:08 pm

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	11/11/2024
Date submitted:	15/11/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Details	
Maintenance Description:	Inspect and assist to disassemble all engine mounts. Lift engine to remove compressor. Kenworth Inspect and carry out clutch adjustment. Submitted By Scott Girard - 15/11/2024 11:13 am
Upload Files:	Invoice_342_from_C__S_Lysaght_Contracting.pdf Submitted By Scott Girard - 15/11/2024 11:13 am

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	11/11/2024
Date submitted:	11/11/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Details	
Maintenance Description:	Replaced cab air bags x4 Checked hyd pressure Replaced mud flap Submitted By Scott Peters - 11/11/2024 12:44 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	27/10/2024
Date submitted:	30/10/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Details	
Maintenance Description:	Inspect prime mover for auto greaser system no functioning correctly Remove bulkhead connector from greasing unit Found no feed at 12V pin Trace wiring back to cabin Found fuse blown Replace fuse Test operation, all ok Submitted By Scott Girard - 30/10/2024 02:03 pm
Upload Files:	Invoice INV-0133.pdf Submitted By Scott Girard - 30/10/2024 02:03 pm

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	10/10/2024
Date submitted:	10/10/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Details	
Maintenance Description:	Basic service 476,459km Ns 500,000km Submitted By Scott Peters - 10/10/2024 12:40 pm
Upload Files:	Basic Service Checklist.docx

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	23/09/2024
Date submitted:	01/10/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Details	
Maintenance Description:	Puncture Truck Tyres (Off and On Vehicle) Submitted By Scott Girard - 01/10/2024 09:59 am
Upload Files:	Invoice312935.pdf Submitted By Scott Girard - 01/10/2024 10:00 am

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	09/09/2024
Date submitted:	09/09/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Details	
Maintenance Description:	Replaced top steering shaft seal Submitted By Scott Peters - 09/09/2024 02:53 pm
Upload Files:	

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	26/07/2024
Date submitted:	31/07/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Details	
Maintenance Description:	LAB - Labour 23/07/2024 Inspect A/C system for low gas, Vac A/C system, removed A/C pipe that appeared to be leaking, cleaned the pipe but found no cracks or holes, fitted the hose, vacuumed system down, gas A/C system Submitted By Scott Girard - 31/07/2024 01:47 pm
Upload Files:	invoice-4680.pdf Submitted By Scott Girard - 31/07/2024 01:47 pm

Upload Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	22/07/2024
Date submitted:	22/07/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Details	
Maintenance Description:	Serviced at 455789kms NS:476,000kms Basic service Submitted By Scott Peters - 22/07/2024 12:26 pm
Upload Files:	Basic Service Checklist.docx

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	30/04/2024
Date submitted:	25/06/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Details	
Maintenance Description:	Bring truck into Worksop inspect A/C issue. Lower bonnet and pressure test system. found high pressure hose from compressor to condenser leaking at fitting. vac system down. remove fitting and hose. solider fitting, crimp to new hose and secure to truck. fill a/ca system with gas. test pressures (OK) system held. raise bonnet. Submitted By Scott Girard - 25/06/2024 09:40 am
Upload Files:	invoice-4460.pdf Submitted By Scott Girard - 25/06/2024 09:40 am

Upload Maintenance Form - 2348M52

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	20/06/2024
Date submitted:	25/06/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Details	
Maintenance Description:	Heavy Truck *Alignment Steer and Drive Beeline JVD Check ball joints king pins track rods and wheel bearings, Measure castor camber and toe of front axle. Adjust toe and rear axles as required.castor or camber. Allow up to 4 hours. Please maintain steer tyre pressures at a min 110psi - Rotate every **For best tyre wear results we recommend steer tyre pressures of between 110 psi - 120 psi. Ensure regular rotations @ 20 to 30 thousand klm ** Submitted By Scott Girard - 25/06/2024 09:31 am
Upload Files:	Invoice1187001.pdf Submitted By Scott Girard - 25/06/2024 09:31 am

Basic Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	30/01/2024
Date submitted:	30/01/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Usage Log	
Odometer Reading (km)	427588 Submitted By Scott Peters - 30/01/2024 02:53 pm

Details	
Maintenance Performed Date:	30/01/2024 Submitted By Scott Peters - 30/01/2024 02:53 pm
Maintenance Description:	Removed and replaced quantity control valve Submitted By Scott Peters - 30/01/2024 02:53 pm
Upload Files:	

Basic Maintenance Form - 2348M52

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	07/12/2023

Plant Details

Owner	S & L Girard Grader Hire
Make	Western Star
Model	4964 SERIES
Type	Prime Mover
VIN / Serial	5KKJAEDR6CPBU3586
Registration	XO52NU
Plant Internal ID	XO52NU
Aquipa Plant ID	2348M52



Usage Log	
Odometer Reading (km)	0 Submitted By Scott Peters - 07/12/2023 03:18 pm

Details	
Maintenance Performed Date:	07/12/2023 Submitted By Scott Peters - 07/12/2023 03:18 pm
Maintenance Description:	Removed front bumper Re weld bumper/bonnet mounts Submitted By Scott Peters - 07/12/2023 03:19 pm
Comments:	Marty Submitted By Scott Peters - 07/12/2023 03:19 pm
Upload Files:	