www.girardgraderhire.com
accounts@girardgraderhire.com.au
0267526462
01/11/2023 - 06/11/2026

Comprehensive Plant Management
https://aquipa.com

Upload Maintenance Form - 2348M29

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	10/08/2026
Date submitted:	10/08/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Toyota
Model	Hilux SINGLE CAB
Type	4WD
VIN / Serial	MR0DZ22G300002999
Registration	DC3GQ
Plant Internal ID	DC39GQ
Aquipa Plant ID	2348M29



Maintenance Upload Details	
Maintenance Description:	Steven Serviced at 311,275km Service at 321,000kms Submitted By Scott Peters - 10/08/2026 11:48 am
Upload Files:	Basic Service Checklist.docx Submitted By Scott Peters - 10/08/2026 11:48 am

Upload Maintenance Form - 2348M29

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	18/04/2026
Date submitted:	22/04/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Toyota
Model	Hilux SINGLE CAB
Type	4WD
VIN / Serial	MR0DZ22G300002999
Registration	DC3GQ
Plant Internal ID	DC39GQ
Aquipa Plant ID	2348M29



Maintenance Upload Details	
Maintenance Description:	inspect vehicle for battery light present on dash start vehicle inspect vehicle for bearing noise to be coming from alternator remove fan belt and inspect alternator pulley found alternator requires replacing remove air box and components to gain access remove and replace alternator refit belt and previously removed components Submitted By Scott Girard - 22/04/2026 10:16 am
Upload Files:	

Upload Maintenance Form - 2348M29

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	11/02/2026
Date submitted:	18/02/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Toyota
Model	Hilux SINGLE CAB
Type	4WD
VIN / Serial	MR0DZ22G300002999
Registration	DC3GQ
Plant Internal ID	DC39GQ
Aquipa Plant ID	2348M29



Maintenance Upload Details	
Maintenance Description:	drove vehicle onto hoist and was a bad grinding crunch noise coming from the front lifted the vehicle checked cv shaft all okay drained the differential oil front and the oil was very burnt and grey the front differential will need to replaced Submitted By Scott Girard - 18/02/2026 02:36 pm
Upload Files:	

Upload Maintenance Form - 2348M29

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	11/02/2026
Date submitted:	12/02/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Toyota
Model	Hilux SINGLE CAB
Type	4WD
VIN / Serial	MR0DZ22G300002999
Registration	DC3GQ
Plant Internal ID	DC39GQ
Aquipa Plant ID	2348M29



Maintenance Upload Details	
Maintenance Description:	bad grinding crunch noise coming from the front, lifted vehicle checked cv shaft all okay drained the differential oil front and the oil was very burnt and grey the front differential will need to be replaced Submitted By Scott Girard - 12/02/2026 02:11 pm
Upload Files:	

Upload Maintenance Form - 2348M29

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	14/01/2026
Date submitted:	14/01/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Toyota
Model	Hilux SINGLE CAB
Type	4WD
VIN / Serial	MR0DZ22G300002999
Registration	DC3GQ
Plant Internal ID	DC39GQ
Aquipa Plant ID	2348M29



Maintenance Upload Details	
Maintenance Description:	Make mounting plates and mount new air compressor to Ute Submitted By Scott Peters - 14/01/2026 08:01 pm
Upload Files:	

Upload Maintenance Form - 2348M29

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	14/01/2026
Date submitted:	14/01/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Toyota
Model	Hilux SINGLE CAB
Type	4WD
VIN / Serial	MR0DZ22G300002999
Registration	DC3GQ
Plant Internal ID	DC39GQ
Aquipa Plant ID	2348M29



Maintenance Upload Details	
Maintenance Description:	Serviced at 300879km Next service at 311,000kms Submitted By Scott Peters - 14/01/2026 09:46 am
Upload Files:	Basic Service Checklist.docx

Upload Maintenance Form - 2348M29

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	23/06/2025
Date submitted:	10/07/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Toyota
Model	Hilux SINGLE CAB
Type	4WD
VIN / Serial	MR0DZ22G300002999
Registration	DC3GQ
Plant Internal ID	DC39GQ
Aquipa Plant ID	2348M29



Maintenance Upload Details	
Maintenance Description:	2 x BF Goodrich 265/60R18 119/116Q MUD TERR Wheel alignment 1x Submitted By Scott Girard - 10/07/2025 11:14 am
Upload Files:	

Upload Maintenance Form - 2348M29

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	13/02/2025
Date submitted:	17/02/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Toyota
Model	Hilux SINGLE CAB
Type	4WD
VIN / Serial	MR0DZ22G300002999
Registration	DC3GQ
Plant Internal ID	DC39GQ
Aquipa Plant ID	2348M29



Details	
Maintenance Description:	Replace engine tappet cover gasket, rear brakes, rear wheel cylinders. Bleed brakes and adjust rear brake shoes, check for leaks all OK Labour by Harborne Auto Electrical & AC Pty Ltd - INV-0297 Submitted By Scott Girard - 17/02/2025 12:41 pm
Upload Files:	

Upload Maintenance Form - 2348M29

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	13/02/2025
Date submitted:	17/02/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Toyota
Model	Hilux SINGLE CAB
Type	4WD
VIN / Serial	MR0DZ22G300002999
Registration	DC3GQ
Plant Internal ID	DC39GQ
Aquipa Plant ID	2348M29



Details	
Maintenance Description:	Remove dash and HVAC box due to evaporator being blocked. - Replace evaporator core, TX Valve and O-rings, evacuate system and charge with 550g of refrigerant, bleed cooling system, Test OK Parts and labour supplied by Harborne Auto Electrical & AC Pty Ltd - INV-0296 Submitted By Scott Girard - 17/02/2025 12:37 pm
Upload Files:	

Upload Maintenance Form - 2348M29

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	24/11/2024
Date submitted:	26/11/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Toyota
Model	Hilux SINGLE CAB
Type	4WD
VIN / Serial	MR0DZ22G300002999
Registration	DC3GQ
Plant Internal ID	DC39GQ
Aquipa Plant ID	2348M29



Details	
Maintenance Description:	REGO: DC39GQ Inspect vehicle for no horn and cruise control not working Found spiral cable to be U/S Order replacement part Remove and replace Spiral cable Test operation, all o Submitted By Scott Girard - 26/11/2024 10:27 am
Upload Files:	Invoice INV-0121.pdf Submitted By Scott Girard - 26/11/2024 10:27 am

Upload Maintenance Form - 2348M29

Performed by:	Marty Van Vegchel (martyvanvegchel@hotmail.com) at S & L Girard Grader Hire
Date performed:	04/06/2024
Date submitted:	04/06/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Toyota
Model	Hilux SINGLE CAB
Type	4WD
VIN / Serial	MR0DZ22G300002999
Registration	DC3GQ
Plant Internal ID	DC39GQ
Aquipa Plant ID	2348M29



Details	
Maintenance Description:	- Replace power steering rack. - Replace universal joints in front drive shaft. 284697km Submitted By Marty Van Vegchel - 04/06/2024 03:27 pm
Upload Files:	

Upload Maintenance Form - 2348M29

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	29/05/2024
Date submitted:	29/05/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Toyota
Model	Hilux SINGLE CAB
Type	4WD
VIN / Serial	MR0DZ22G300002999
Registration	DC3GQ
Plant Internal ID	DC39GQ
Aquipa Plant ID	2348M29



Details	
Maintenance Description:	Replaced driving light bulbs Submitted By Scott Peters - 29/05/2024 02:51 pm
Upload Files:	

Upload Maintenance Form - 2348M29

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	15/05/2024
Date submitted:	15/05/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Toyota
Model	Hilux SINGLE CAB
Type	4WD
VIN / Serial	MR0DZ22G300002999
Registration	DC3GQ
Plant Internal ID	DC39GQ
Aquipa Plant ID	2348M29



Details	
Maintenance Description:	Serviced at 283,567km Next service at 294,000km Submitted By Scott Peters - 15/05/2024 07:38 am
Upload Files:	Basic Service Checklist.docx

Basic Maintenance Form - 2348M29

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	09/01/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Toyota
Model	Hilux SINGLE CAB
Type	4WD
VIN / Serial	MR0DZ22G300002999
Registration	DC3GQ
Plant Internal ID	DC39GQ
Aquipa Plant ID	2348M29



Usage Log	
Odometer Reading (km)	278985 Submitted By Scott Peters - 09/01/2024 04:15 pm

Details	
Maintenance Performed Date:	09/01/2024 Submitted By Scott Peters - 09/01/2024 04:15 pm
Maintenance Description:	Complete new springs and shocks on rear end Submitted By Scott Peters - 09/01/2024 04:15 pm
Upload Files:	

Basic Maintenance Form - 2348M29

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	10/11/2023

Plant Details

Owner	S & L Girard Grader Hire
Make	Toyota
Model	Hilux SINGLE CAB
Type	4WD
VIN / Serial	MR0DZ22G300002999
Registration	DC3GQ
Plant Internal ID	DC39GQ
Aquipa Plant ID	2348M29



Usage Log	
Odometer Reading (km)	274851 Submitted By Scott Girard - 10/11/2023 02:25 pm

Details	
Maintenance Performed Date:	06/11/2023 Submitted By Scott Girard - 10/11/2023 02:26 pm
Maintenance Description:	replaced 2x tyres Submitted By Scott Girard - 10/11/2023 02:27 pm
Comments:	2x BF goodrich 265/60R18 fitted and supplied by jukes and sons tyre centre moree Submitted By Scott Girard - 10/11/2023 02:28 pm
Upload Files:	