

www.girardgraderhire.com
accounts@girardgraderhire.com.au
0267526462
01/11/2023 - 06/11/2026



Comprehensive Plant Management
https://aquipa.com

Upload Maintenance Form - 2348M54

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	16/04/2026
Date submitted:	23/04/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	ATAN86A
Type	Trailer
VIN / Serial	6T9T24ABF50ADG022
Registration	YN43YX
Plant Internal ID	YN43YX
Aquipa Plant ID	2348M54



Maintenance Upload Details	
Maintenance Description:	2 x satec tyres Submitted By Scott Girard - 23/04/2026 01:41 pm
Upload Files:	

Upload Maintenance Form - 2348M54

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	15/04/2026
Date submitted:	15/04/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	ATAN86A
Type	Trailer
VIN / Serial	6T9T24ABF50ADG022
Registration	YN43YX
Plant Internal ID	YN43YX
Aquipa Plant ID	2348M54



Maintenance Upload Details	
Maintenance Description:	Replaced FF right hand brake shoes and drum Submitted By Scott Peters - 15/04/2026 03:21 pm
Upload Files:	

Upload Maintenance Form - 2348M54

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	23/08/2025
Date submitted:	16/09/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	ATAN86A
Type	Trailer
VIN / Serial	6T9T24ABF50ADG022
Registration	YN43YX
Plant Internal ID	YN43YX
Aquipa Plant ID	2348M54



Maintenance Upload Details	
Maintenance Description:	1 x tyre satec 11r22.5 Submitted By Scott Girard - 16/09/2025 11:24 am
Upload Files:	

Upload Maintenance Form - 2348M54

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	22/05/2025
Date submitted:	28/05/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	ATAN86A
Type	Trailer
VIN / Serial	6T9T24ABF50ADG022
Registration	YN43YX
Plant Internal ID	YN43YX
Aquipa Plant ID	2348M54



Maintenance Upload Details	
Maintenance Description:	repair cracks where needed on dog trailer Submitted By Scott Girard - 28/05/2025 08:41 am
Upload Files:	

Upload Maintenance Form - 2348M54

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	29/04/2025
Date submitted:	29/04/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	ATAN86A
Type	Trailer
VIN / Serial	6T9T24ABF50ADG022
Registration	YN43YX
Plant Internal ID	YN43YX
Aquipa Plant ID	2348M54



Maintenance Upload Details	
Maintenance Description:	Replaced tailgate actuator Submitted By Scott Peters - 29/04/2025 02:48 pm
Upload Files:	

Upload Maintenance Form - 2348M54

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	06/12/2024
Date submitted:	13/03/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	ATAN86A
Type	Trailer
VIN / Serial	6T9T24ABF50ADG022
Registration	YN43YX
Plant Internal ID	YN43YX
Aquipa Plant ID	2348M54



Maintenance Upload Details	
Maintenance Description:	replaced tyres and rotation vortex 11R22.5 4x rotation tyres auto/4wd INV - 316939 jukes and sons Submitted By Scott Girard - 13/03/2025 02:36 pm
Upload Files:	

Upload Maintenance Form - 2348M54

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	11/12/2024
Date submitted:	13/03/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	ATAN86A
Type	Trailer
VIN / Serial	6T9T24ABF50ADG022
Registration	YN43YX
Plant Internal ID	YN43YX
Aquipa Plant ID	2348M54



Maintenance Upload Details	
Maintenance Description:	replaced tyre 1x vortex 11R22.5 INV - 317139 jukes and sons Submitted By Scott Girard - 13/03/2025 02:33 pm
Upload Files:	

Upload Maintenance Form - 2348M54

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	06/12/2024
Date submitted:	10/12/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	ATAN86A
Type	Trailer
VIN / Serial	6T9T24ABF50ADG022
Registration	YN43YX
Plant Internal ID	YN43YX
Aquipa Plant ID	2348M54



Details	
Maintenance Description:	VORTEX 11R22.5 (16PR) VA08 ALL POS (XZY) ROTA ROTATION TYRES AUTO/4WD Submitted By Scott Girard - 10/12/2024 11:06 am
Upload Files:	Invoice316939.pdf Submitted By Scott Girard - 10/12/2024 11:06 am

Upload Maintenance Form - 2348M54

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	02/12/2024
Date submitted:	02/12/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	ATAN86A
Type	Trailer
VIN / Serial	6T9T24ABF50ADG022
Registration	YN43YX
Plant Internal ID	YN43YX
Aquipa Plant ID	2348M54



Details	
Maintenance Description:	Replaced left trailer light Submitted By Scott Peters - 02/12/2024 01:41 pm
Upload Files:	

Upload Maintenance Form - 2348M54

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	30/10/2024
Date submitted:	30/10/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	ATAN86A
Type	Trailer
VIN / Serial	6T9T24ABF50ADG022
Registration	YN43YX
Plant Internal ID	YN43YX
Aquipa Plant ID	2348M54



Details	
Maintenance Description:	Source and disassemble rear right hand rocker box bushes. Fit new bushes and pin. Found that spring hangers need to be replaced so no further bushes were replaced. Submitted By Scott Girard - 30/10/2024 02:35 pm
Upload Files:	Invoice314854.pdf Submitted By Scott Girard - 30/10/2024 02:35 pm

Upload Maintenance Form - 2348M54

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	22/10/2024
Date submitted:	22/10/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	ATAN86A
Type	Trailer
VIN / Serial	6T9T24ABF50ADG022
Registration	YN43YX
Plant Internal ID	YN43YX
Aquipa Plant ID	2348M54



Details	
Maintenance Description:	Fixed tail gate actuator Submitted By Scott Peters - 22/10/2024 05:17 pm
Upload Files:	

Upload Maintenance Form - 2348M54

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	09/09/2024
Date submitted:	10/09/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	ATAN86A
Type	Trailer
VIN / Serial	6T9T24ABF50ADG022
Registration	YN43YX
Plant Internal ID	YN43YX
Aquipa Plant ID	2348M54



Details	
Maintenance Description:	VORTEX 11R22.5 (16PR) VA08 ALL POS (XZY) ROTATION LIGHT TRUCK TYRES Submitted By Scott Girard - 10/09/2024 09:22 am
Upload Files:	Invoice312285.pdf Submitted By Scott Girard - 10/09/2024 09:23 am

Upload Maintenance Form - 2348M54

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	13/08/2024
Date submitted:	13/08/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	ATAN86A
Type	Trailer
VIN / Serial	6T9T24ABF50ADG022
Registration	YN43YX
Plant Internal ID	YN43YX
Aquipa Plant ID	2348M54



Details	
Maintenance Description:	Replaced quick release valve for tail gate Submitted By Scott Peters - 13/08/2024 11:25 am
Upload Files:	

Upload Maintenance Form - 2348M54

Performed by:	Marty Van Vegchel (martyvanvegchel@hotmail.com) at S & L Girard Grader Hire
Date performed:	18/07/2024
Date submitted:	18/07/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	ATAN86A
Type	Trailer
VIN / Serial	6T9T24ABF50ADG022
Registration	YN43YX
Plant Internal ID	YN43YX
Aquipa Plant ID	2348M54



Details	
Maintenance Description:	Replace drawbar springs. Submitted By Marty Van Vegchel - 18/07/2024 01:06 pm
Upload Files:	
Add Photos:	 Submitted By Marty Van Vegchel - 18/07/2024 01:06 pm

Upload Maintenance Form - 2348M54

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	03/06/2024
Date submitted:	03/06/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	ATAN86A
Type	Trailer
VIN / Serial	6T9T24ABF50ADG022
Registration	YN43YX
Plant Internal ID	YN43YX
Aquipa Plant ID	2348M54



Details	
Maintenance Description:	Replaced air bag on rear of trailer Submitted By Scott Peters - 03/06/2024 08:26 am
Upload Files:	

Upload Maintenance Form - 2348M54

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	27/05/2024
Date submitted:	27/05/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	ATAN86A
Type	Trailer
VIN / Serial	6T9T24ABF50ADG022
Registration	YN43YX
Plant Internal ID	YN43YX
Aquipa Plant ID	2348M54



Details	
Maintenance Description:	Rewired trailer plug Found broken clearance light wire and repaired Repaired rear flashing lights Submitted By Scott Peters - 27/05/2024 09:10 am
Upload Files:	

Basic Maintenance Form - 2348M54

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	19/04/2024
Date submitted:	19/04/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	ATAN86A
Type	Trailer
VIN / Serial	6T9T24ABF50ADG022
Registration	YN43YX
Plant Internal ID	YN43YX
Aquipa Plant ID	2348M54



Usage Log	
Odometer Reading (km)	0 Submitted By Scott Peters - 19/04/2024 12:54 pm

Details	
Maintenance Performed Date:	19/04/2024 Submitted By Scott Peters - 19/04/2024 12:54 pm
Maintenance Description:	Rear front axle left brake shoes replaced 2 clearance lights left hand side. Submitted By Scott Peters - 19/04/2024 12:54 pm
Upload Files:	

Basic Maintenance Form - 2348M54

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	13/03/2024
Date submitted:	13/03/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	ATAN86A
Type	Trailer
VIN / Serial	6T9T24ABF50ADG022
Registration	YN43YX
Plant Internal ID	YN43YX
Aquipa Plant ID	2348M54



Usage Log	
Odometer Reading (km)	0 Submitted By Scott Peters - 13/03/2024 12:04 pm

Details	
Maintenance Performed Date:	13/03/2024 Submitted By Scott Peters - 13/03/2024 12:04 pm
Maintenance Description:	Replaced wiring for lights. Replaced back axle both brake boosters Submitted By Scott Peters - 13/03/2024 12:05 pm
Upload Files:	

Basic Maintenance Form - 2348M54

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	12/02/2024
Date submitted:	12/02/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	ATAN86A
Type	Trailer
VIN / Serial	6T9T24ABF50ADG022
Registration	YN43YX
Plant Internal ID	YN43YX
Aquipa Plant ID	2348M54



Usage Log	
Odometer Reading (km)	0 Submitted By Scott Peters - 12/02/2024 12:23 pm

Details	
Maintenance Performed Date:	12/02/2024 Submitted By Scott Peters - 12/02/2024 12:23 pm
Maintenance Description:	Seated air bags correctly due to no air supply when driven. Replaced rear ride height valve Replaced rear right air bag. Fixed light wiring Submitted By Scott Peters - 12/02/2024 12:24 pm
Upload Files:	

Basic Maintenance Form - 2348M54

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	11/01/2024
Date submitted:	16/01/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	ATAN86A
Type	Trailer
VIN / Serial	6T9T24ABF50ADG022
Registration	YN43YX
Plant Internal ID	YN43YX
Aquipa Plant ID	2348M54



Usage Log

Details	
Maintenance Performed Date:	11/01/2024 Submitted By Scott Girard - 16/01/2024 03:37 pm
Maintenance Description:	Replaced tyre Submitted By Scott Girard - 16/01/2024 03:37 pm
Comments:	1x Vortex 11R22.5 All POS tyre fitted and supplied by Jukes & Sons Tyre Centre Moree Submitted By Scott Girard - 16/01/2024 03:38 pm
Upload Files:	