www.girardgraderhire.com
accounts@girardgraderhire.com.au
0267526462
01/11/2023 - 06/11/2026

Comprehensive Plant Management
https://aquipa.com

Upload Maintenance Form - 2348M22

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	09/07/2025
Date submitted:	31/07/2025

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Toyota	
Model	Hilux	
Type	Passenger Vehicle	
VIN / Serial	MR0FZ29G801538985	
Registration	AM57FN	
Plant Internal ID	AM57FN	
Aquipa Plant ID	2348M22	

Maintenance Upload Details	
Maintenance Description:	puncture tyres 1x Submitted By Scott Girard - 31/07/2025 10:12 am
Upload Files:	

Upload Maintenance Form - 2348M22

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	09/07/2025
Date submitted:	10/07/2025

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Toyota	
Model	Hilux	
Type	Passenger Vehicle	
VIN / Serial	MR0FZ29G801538985	
Registration	AM57FN	
Plant Internal ID	AM57FN	
Aquipa Plant ID	2348M22	

Maintenance Upload Details	
Maintenance Description:	1 x puncture tyre Submitted By Scott Girard - 10/07/2025 09:15 am
Upload Files:	

Upload Maintenance Form - 2348M22

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	16/04/2025
Date submitted:	16/04/2025

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Toyota	
Model	Hilux	
Type	Passenger Vehicle	
VIN / Serial	MR0FZ29G801538985	
Registration	AM57FN	
Plant Internal ID	AM57FN	
Aquipa Plant ID	2348M22	

Maintenance Upload Details	
Maintenance Description:	Serviced at 636,233kms NeXT service 646,000kms Submitted By Scott Peters - 16/04/2025 01:03 pm
Upload Files:	Basic Service Checklist.docx

Upload Maintenance Form - 2348M22

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	04/04/2025
Date submitted:	04/04/2025

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Toyota	
Model	Hilux	
Type	Passenger Vehicle	
VIN / Serial	MR0FZ29G801538985	
Registration	AM57FN	
Plant Internal ID	AM57FN	
Aquipa Plant ID	2348M22	

Maintenance Upload Details	
Maintenance Description:	Replaced alternator and belt At 636,128kms Submitted By Scott Peters - 04/04/2025 08:49 am
Upload Files:	

Upload Maintenance Form - 2348M22

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	28/01/2025
Date submitted:	28/01/2025

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Toyota	
Model	Hilux	
Type	Passenger Vehicle	
VIN / Serial	MR0FZ29G801538985	
Registration	AM57FN	
Plant Internal ID	AM57FN	
Aquipa Plant ID	2348M22	

Details	
Maintenance Description:	Fitted new left rear door glass Supplied by hardman windscreens Submitted By Scott Peters - 28/01/2025 02:05 pm
Upload Files:	

Upload Maintenance Form - 2348M22

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	06/05/2024
Date submitted:	06/05/2024

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Toyota	
Model	Hilux	
Type	Passenger Vehicle	
VIN / Serial	MR0FZ29G801538985	
Registration	AM57FN	
Plant Internal ID	AM57FN	
Aquipa Plant ID	2348M22	

Details	
Maintenance Description:	Rebuild rear brakes. Replace axles seals Replaced right hand brake cable 630214kms Submitted By Scott Peters - 06/05/2024 03:14 pm
Upload Files:	

Basic Maintenance Form - 2348M22

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	12/03/2024
Date submitted:	12/03/2024

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Toyota	
Model	Hilux	
Type	Passenger Vehicle	
VIN / Serial	MR0FZ29G801538985	
Registration	AM57FN	
Plant Internal ID	AM57FN	
Aquipa Plant ID	2348M22	

Usage Log	
Odometer Reading (km)	628858 Submitted By Scott Peters - 12/03/2024 11:11 am

Details	
Maintenance Performed Date:	12/03/2024 Submitted By Scott Peters - 12/03/2024 11:11 am
Maintenance Description:	Diagnosed and fixed rear taillight and brakes Submitted By Scott Peters - 12/03/2024 11:12 am
Upload Files:	

Basic Maintenance Form - 2348M22

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	12/02/2024
Date submitted:	12/02/2024

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Toyota	
Model	Hilux	
Type	Passenger Vehicle	
VIN / Serial	MR0FZ29G801538985	
Registration	AM57FN	
Plant Internal ID	AM57FN	
Aquipa Plant ID	2348M22	

Usage Log	
Odometer Reading (km)	627000 Submitted By Scott Peters - 12/02/2024 12:30 pm

Details	
Maintenance Performed Date:	12/02/2024 Submitted By Scott Peters - 12/02/2024 12:30 pm
Maintenance Description:	New front shocks New tie rod ends New sway bar links New upper ball joints New lower control arms Swap tyres. Wheel alignment Submitted By Scott Peters - 12/02/2024 12:31 pm
Comments:	Dylan Submitted By Scott Peters - 12/02/2024 12:31 pm
Upload Files:	

Basic Maintenance Form - 2348M22

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	14/12/2023

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Toyota	
Model	Hilux	
Type	Passenger Vehicle	
VIN / Serial	MR0FZ29G801538985	
Registration	AM57FN	
Plant Internal ID	AM57FN	
Aquipa Plant ID	2348M22	

Usage Log	
Odometer Reading (km)	625587 Submitted By Scott Peters - 14/12/2023 11:09 am

Details	
Maintenance Performed Date:	14/12/2023 Submitted By Scott Peters - 14/12/2023 11:09 am
Maintenance Description:	Basic service Submitted By Scott Peters - 14/12/2023 11:09 am
Upload Files:	

Basic Maintenance Form - 2348M22

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	11/12/2023

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Toyota	
Model	Hilux	
Type	Passenger Vehicle	
VIN / Serial	MR0FZ29G801538985	
Registration	AM57FN	
Plant Internal ID	AM57FN	
Aquipa Plant ID	2348M22	

Usage Log	
Odometer Reading (km)	625260 Submitted By Scott Girard - 11/12/2023 02:38 pm

Details	
Maintenance Performed Date:	27/11/2023 Submitted By Scott Girard - 11/12/2023 02:38 pm
Maintenance Description:	Replace windscreen Submitted By Scott Girard - 11/12/2023 02:38 pm
Comments:	Supply and fit W132 windscreen Submitted By Scott Girard - 11/12/2023 02:38 pm
Upload Files:	