www.girardgraderhire.com
accounts@girardgraderhire.com.au
0267526462
01/11/2023 - 06/11/2026

Comprehensive Plant Management
https://aquipa.com

**Upload Maintenance Form - 2348M92**

| | |
|---|---|
| Performed by: | Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire |
| Date performed: | 28/08/2026 |
| Date submitted: | 03/09/2026 |

**Plant Details**

| | |
|---|---|
| Owner | S & L Girard Grader Hire |
| Make | AllRoad |
| Model | tri-axle |
| Type | Trailer - Semi Trailer |
| VIN / Serial | 6T9T25WA1D04WX002 |
| Registration | YO04GN |
| Plant Internal ID | YO04GN |
| Aquipa Plant ID | 2348M92 |

Plant Image is not available

| **Maintenance Upload Details** | |
|---|---|
| Maintenance Description: | Regroove tyres to trailer x 4 Invoice_345433<br>Submitted By Scott Girard - 03/09/2026 11:21 am |
| Upload Files: | Invoice345433.pdf<br>Submitted By Scott Girard - 03/09/2026 11:21 am |

**Upload Maintenance Form - 2348M92**

| | |
|---|---|
| Performed by: | Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire |
| Date performed: | 28/08/2026 |
| Date submitted: | 28/08/2026 |

**Plant Details**

| | | |
|---|---|---|
| Owner | S & L Girard Grader Hire | Plant Image is not available |
| Make | AllRoad | |
| Model | tri-axle | |
| Type | Trailer - Semi Trailer | |
| VIN / Serial | 6T9T25WA1D04WX002 | |
| Registration | YO04GN | |
| Plant Internal ID | YO04GN | |
| Aquipa Plant ID | 2348M92 | |

| **Maintenance Upload Details** | |
|---|---|
| Maintenance Description: | Replaces rear axle 8 track rod bushes<br>Submitted By Scott Peters - 28/08/2026 05:10 pm |
| Upload Files: | |

**Upload Maintenance Form - 2348M92**

| | |
|---|---|
| Performed by: | Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire |
| Date performed: | 11/08/2026 |
| Date submitted: | 12/08/2026 |

**Plant Details**

| | | |
|---|---|---|
| Owner | S & L Girard Grader Hire | Plant Image is not available |
| Make | AllRoad | |
| Model | tri-axle | |
| Type | Trailer - Semi Trailer | |
| VIN / Serial | 6T9T25WA1D04WX002 | |
| Registration | YO04GN | |
| Plant Internal ID | YO04GN | |
| Aquipa Plant ID | 2348M92 | |

| **Maintenance Upload Details** | |
|---|---|
| Maintenance Description: | Tail light repairs Clearance lights replaced<br>Submitted By Scott Peters - 12/08/2026 07:59 am |
| Upload Files: | |

**Upload Maintenance Form - 2348M92**

| | |
|---|---|
| Performed by: | Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire |
| Date performed: | 09/06/2026 |
| Date submitted: | 09/06/2026 |

**Plant Details**

| | | |
|---|---|---|
| Owner | S & L Girard Grader Hire | Plant Image is not available |
| Make | AllRoad | |
| Model | tri-axle | |
| Type | Trailer - Semi Trailer | |
| VIN / Serial | 6T9T25WA1D04WX002 | |
| Registration | YO04GN | |
| Plant Internal ID | YO04GN | |
| Aquipa Plant ID | 2348M92 | |

| **Maintenance Upload Details** | |
|---|---|
| Maintenance Description: | 2 x Satec 11R22.5<br>Submitted By Scott Girard - 09/06/2026 02:08 pm |
| Upload Files: | |

**Upload Maintenance Form - 2348M92**

| | |
|---|---|
| Performed by: | Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire |
| Date performed: | 10/12/2025 |
| Date submitted: | 09/12/2025 |

**Plant Details**

| | | |
|---|---|---|
| Owner | S & L Girard Grader Hire | Plant Image is not available |
| Make | AllRoad | |
| Model | tri-axle | |
| Type | Trailer - Semi Trailer | |
| VIN / Serial | 6T9T25WA1D04WX002 | |
| Registration | YO04GN | |
| Plant Internal ID | YO04GN | |
| Aquipa Plant ID | 2348M92 | |

| **Maintenance Upload Details** | |
|---|---|
| Maintenance Description: | Replaced damaged hyd hoses for side tipper roof<br>Submitted By Scott Peters - 09/12/2025 08:19 am |
| Upload Files: | |

**Upload Maintenance Form - 2348M92**

| | |
|---|---|
| Performed by: | Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire |
| Date performed: | 10/07/2025 |
| Date submitted: | 10/07/2025 |

**Plant Details**

| | | |
|---|---|---|
| Owner | S & L Girard Grader Hire | Plant Image is not available |
| Make | AllRoad | |
| Model | tri-axle | |
| Type | Trailer - Semi Trailer | |
| VIN / Serial | 6T9T25WA1D04WX002 | |
| Registration | YO04GN | |
| Plant Internal ID | YO04GN | |
| Aquipa Plant ID | 2348M92 | |

| **Maintenance Upload Details** | |
|---|---|
| Maintenance Description: | Adjusted no 1 axle front left side wheel bearing<br>Submitted By Scott Peters - 10/07/2025 10:52 am |
| Upload Files: | |

**Upload Maintenance Form - 2348M92**

| | |
|---|---|
| Performed by: | Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire |
| Date performed: | 28/05/2025 |
| Date submitted: | 28/05/2025 |

**Plant Details**

| | | |
|---|---|---|
| Owner | S & L Girard Grader Hire | Plant Image is not available |
| Make | AllRoad | |
| Model | tri-axle | |
| Type | Trailer - Semi Trailer | |
| VIN / Serial | 6T9T25WA1D04WX002 | |
| Registration | YO04GN | |
| Plant Internal ID | YO04GN | |
| Aquipa Plant ID | 2348M92 | |

| **Maintenance Upload Details** | |
|---|---|
| Maintenance Description: | Replaced all brake shoes Replaced all wheel bearings Replaced all s cam and tubes Replaced bushes Replaced all slack adjuster Replaced broken leaf on left front spring Replace axle1 and axle 2 torque rod bushes Swapped rims over to alloy Torqued wheel nuts 122521kms on wheel hub meter KF21 K hitch axle<br>Submitted By Scott Peters - 28/05/2025 10:53 am |
| Upload Files: | |