

www.girardgraderhire.com
accounts@girardgraderhire.com.au
0267526462
01/11/2023 - 06/11/2026



Comprehensive Plant Management
https://aquipa.com

Upload Maintenance Form - 2348M97

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	17/08/2026
Date submitted:	17/08/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	HINO
Model	FMSJ
Type	
VIN / Serial	JHOFM8JRKXXX12130
Registration	XO79SP
Plant Internal ID	XO79SP
Aquipa Plant ID	2348M97



Maintenance Upload Details	
Maintenance Description:	Diagnose fuel pump not working for fill pump Submitted By Scott Peters - 17/08/2026 12:05 pm
Upload Files:	

Upload Maintenance Form - 2348M97

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	12/08/2026
Date submitted:	12/08/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	HINO
Model	FMSJ
Type	
VIN / Serial	JHOFM8JRKXXX12130
Registration	XO79SP
Plant Internal ID	XO79SP
Aquipa Plant ID	2348M97



Maintenance Upload Details	
Maintenance Description:	Wired in red light on PTO switch Submitted By Scott Peters - 12/08/2026 02:14 pm
Upload Files:	

Upload Maintenance Form - 2348M97

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	01/07/2026
Date submitted:	01/07/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	HINO
Model	FMSJ
Type	
VIN / Serial	JHOFM8JRKXXX12130
Registration	XO79SP
Plant Internal ID	XO79SP
Aquipa Plant ID	2348M97



Maintenance Upload Details	
Maintenance Description:	Fitted new rear centre fan. Fitted new air intake manifold. Fitted new air filter housing . Removed ignition couldn't fix,so ordered new one Submitted By Scott Peters - 01/07/2026 04:20 pm
Upload Files:	

Upload Maintenance Form - 2348M97

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	09/06/2026
Date submitted:	09/06/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	HINO
Model	FMSJ
Type	
VIN / Serial	JHOFM8JRKXXX12130
Registration	XO79SP
Plant Internal ID	XO79SP
Aquipa Plant ID	2348M97



Maintenance Upload Details	
Maintenance Description:	Removed and replaced water pump. Replaced air con belt and fix belt tensioner Replaced main belt tensioner. Topped up with coolant and test run in shed 238,343kms Submitted By Scott Peters - 09/06/2026 04:41 pm
Upload Files:	

Upload Maintenance Form - 2348M97

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	23/02/2026
Date submitted:	24/02/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	HINO
Model	FMSJ
Type	
VIN / Serial	JHOFM8JRKXXX12130
Registration	XO79SP
Plant Internal ID	XO79SP
Aquipa Plant ID	2348M97



Maintenance Upload Details	
Maintenance Description:	Rebuilt water pump on truck Submitted By Scott Peters - 24/02/2026 04:45 pm
Upload Files:	

Upload Maintenance Form - 2348M97

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	29/11/2025
Date submitted:	11/12/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	HINO
Model	FMSJ
Type	
VIN / Serial	JHOFM8JRKXXX12130
Registration	XO79SP
Plant Internal ID	XO79SP
Aquipa Plant ID	2348M97



Maintenance Upload Details	
Maintenance Description:	1 windforce tyres Submitted By Scott Girard - 11/12/2025 02:11 pm
Upload Files:	

Upload Maintenance Form - 2348M97

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	21/11/2025
Date submitted:	22/11/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	HINO
Model	FMSJ
Type	
VIN / Serial	JHOFM8JRKXXX12130
Registration	XO79SP
Plant Internal ID	XO79SP
Aquipa Plant ID	2348M97



Maintenance Upload Details	
Maintenance Description:	Basic engine service at 226,975kms Next service at 246,000kms Checked transmission oil. Fitted new diesel fill pump for as required Submitted By Scott Peters - 22/11/2025 08:38 am
Upload Files:	Basic Service Checklist.docx