

EK16-1



REPAIR SHOP SERVICE REPORT

DATE	16 APRIL 2025	WORK ORDER	48891
CUSTOMER	GLOBAL	MECHANIC	AARON
MAKE	DETROIT	HOURL METER	123.58
MODEL	10435000	SERIAL #	4A213189
UNIT/RIG #	GPS 9114	ARRANGEMENT #	

REPAIRS PERFORMED:

REMOVE PUMP AND ENGINE FROM BUILDING. ENGINE HAD NO OIL ON THE DIP STICK, OPENED DRAIN TO INSPECT OIL AND ABOUT A TABLESPOON OF COOLANT CAME OUT WITH SOME OIL. ADD 4L COOLANT, ADD 12L OF OIL. START UNIT. UNIT RUNS WELL, 45PSI OIL PRESSURE AT 1800RPM, TRANSMISSION WORKS.

K16-1