



REPAIR SHOP SERVICE REPORT

| | | | |
|------------|---------------|---------------|-----------|
| DATE | 16 APRIL 2025 | WORK ORDER | 48891 |
| CUSTOMER | GLOBAL | MECHANIC | AARON |
| MAKE | DETROIT | HOURLY RATE | 123.58 |
| MODEL | 10337000 | SERIAL # | 3A0095693 |
| UNIT/RIG # | GPS 9115 | ARRANGEMENT # | |

REPAIRS PERFORMED:

REMOVE PUMP AND ENGINE FROM BUILDING. ADD 4L COOLANT, START UNIT. UNIT RUNS WELL, 55PSI OIL PRESSURE AT 1800RPM, TRANSMISSION WORKS.

K16-2