

N11-1



Vehicle Standards and Inspection

## Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A126341

Station #: 71367

Station Name: Chrome Diesel Repair Ltd.

Technician #: 82380

Technician Name: Marty Bedwell

Signing Officer #: 88805

Signing Officer Name: Lori-Anne Nohnychuk

### Customer Details:

Name: STEADY ENERGY SERVICES INC.

Address: BOX 601, LLOYDMINSTER, Saskatchewan, S9V 0Y7

Inspection Completed Date: 23Jan2025

Inspection Expiry Date: 31Jan2026

### Vehicle Details:

VIN: 5HTDL403275G22122

Hubometer Reading:

Year: 2007

Vehicle Make/Model: TRAILER/TRAILER

Plate: 704 MCX

Jurisdiction: Saskatchewan

Unit: 701L

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.

N11-2



Vehicle Standards and Inspection

## Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A126342

Station #: 71367

Station Name: Chrome Diesel Repair Ltd.

Technician #: 82380

Technician Name: Marty Bedwell

Signing Officer #: 88805

Signing Officer Name: Lori-Anne Nohnychuk

### Customer Details:

Name: STEADY ENERGY SERVICES INC.

Address: BOX 601, LLOYDMINSTER, Saskatchewan, S9V 0Y7

Inspection Completed Date: 23Jan2025

Inspection Expiry Date: 31Jan2026

### Vehicle Details:

VIN: 5HTDL312975F22132

Hubometer Reading:

Year: 2007

Vehicle Make/Model: TRAILER/TRAILER

Plate: 705 MCK

Jurisdiction: Saskatchewan

Unit: 701P

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.