



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A237207

JP7-6

Station #: 70215

Station Name: Federated Co-Operatives Limited

Technician #: 91281

Technician Name: Jamie Lemieux

Signing Officer #: 82283

Signing Officer Name: Lorne Turbuck

Customer Details:

Name: Federated Coop Limited (Petro)

Address: Box 260, Regina, Saskatchewan, S4P3A1

Inspection Completed Date: 22Sep2025

Inspection Expiry Date: 30Sep2026

Vehicle Details:

VIN: 2AEABSAH88R000267

Hubometer Reading:

Year: 2008

Vehicle Make/Model: ADVANCE TRAILER/

Plate: 709 MAV

Jurisdiction: Saskatchewan

Unit: 2631

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70215
Technician #: 91281
Signing Officer #: 82283

Station Name: Federated Co-Operatives Limited
Technician Name: Jamie Lemieux
Signing Officer Name: Lorne Turbuck

Customer Details:

Name: Federated Coop Limited (Petro)

Address: Box 260, Regina, Saskatchewan, S4P3A1

Vehicle Details:

VIN: 2AEABSAH88R000267

Hubometer Reading:

Year: 2008

Vehicle Make/Model: ADVANCE TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
		x		Fire Extinguisher (5)	Out dated.
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
		x		Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
		x		Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (If equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 14/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 13/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 58.0 degrees • Brake Stroke: 2 in

Wheel3-On : Tire Tread Depth: 13/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 9/16 in • Cam Rotation: 92.0 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 14/32 in

Brake(1): No Brake

N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 12/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 13/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 19/32 in • Cam Rotation: 75.0 degrees • Brake Stroke: 1 3/4 in

Wheel3-On : Tire Tread Depth: 12/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 23/32 in • Cam Rotation: 55.0 degrees • Brake Stroke: 1 3/4 in

Wheel4 : Tire Tread Depth: 12/32 in

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 9/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 9/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 45.0 degrees • Brake Stroke: 1 3/4 in

Wheel3-On : Tire Tread Depth: 13/32 in

Wheel 4 : Tire Tread Depth: 13/32 in

Brake(1): No Brake

N/A

PASS - vehicle passes inspection	Decal # A237207	Inspection Completed Date: 22Sep2025
----------------------------------	-----------------	--------------------------------------



Vehicle Standards and Inspection

JP1-7

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A237208

Station #: 70215

Station Name: Federated Co-Operatives Limited

Technician #: 91281

Technician Name: Jamie Lemieux

Signing Officer #: 82283

Signing Officer Name: Lorne Turbuck

Customer Details:

Name: Federated Coop Limited (Petro)

Address: Box 260, Regina, Saskatchewan, S4P3A1

Inspection Completed Date: 22Sep2025

Inspection Expiry Date: 30Sep2026

Vehicle Details:

VIN: 2AEARPAE38R000270

Hubometer Reading:

Year: 2008

Vehicle Make/Model: ADVANCE TRAILER/

Plate: 710 MAV

Jurisdiction: Saskatchewan

Unit: 2632

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70215

Station Name: Federated Co-Operatives Limited

Technician #: 91281

Technician Name: Jamie Lemieux

Signing Officer #: 82283

Signing Officer Name: Lorne Turbuck

Customer Details:

Name: Federated Coop Limited (Petro)

Address: Box 260, Regina, Saskatchewan, S4P3A1

Vehicle Details:

VIN: 2AEARPAE38R000270

Hubometer Reading:

Year: 2008

Vehicle Make/Model: ADVANCE TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
		x		Fire Extinguisher (5)	Out Dated.
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
		x		Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
		x		Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 12/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 10/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 23/32 in • Cam Rotation: 56.0 degrees • Brake Stroke: 1 1/4 in

Wheel3-On : Tire Tread Depth: 13/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 41.0 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 11/32 in

Brake(1): No Brake

N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 12/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 10/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 70.0 degrees • Brake Stroke: 1 5/8 in

Wheel3-On : Tire Tread Depth: 13/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 42.0 degrees • Brake Stroke: 1 3/4 in

Wheel4 : Tire Tread Depth: 11/32 in

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A237208

Inspection Completed Date: 22Sep2025