



Vehicle Standards and Inspection

JP7-10

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A237222

Station #: 70215

Station Name: Federated Co-Operatives Limited

Technician #: 91281

Technician Name: Jamie Lemieux

Signing Officer #: 83382

Signing Officer Name: Tom Fesciuc

Customer Details:

Name: Federated Coop Limited (Petro)

Address: Box 260, Regina, Saskatchewan, S4P3A1

Inspection Completed Date: 16Sep2025

Inspection Expiry Date: 30Sep2026

Vehicle Details:

VIN: 2AEABSAH6YR000266

Hubometer Reading:

Year: 2000

Vehicle Make/Model: ADVANCE TRAILER/

Plate: 574MJP

Jurisdiction: Saskatchewan

Unit: 2809

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70215

Station Name: Federated Co-Operatives Limited

Technician #: 91281

Technician Name: Jamie Lemieux

Signing Officer #: 83382

Signing Officer Name: Tom Fesciuc

Customer Details:

Name: Federated Coop Limited (Petro)

Address: Box 260, Regina, Saskatchewan, S4P3A1

Vehicle Details:

VIN: 2AEABSAH6YR000266

Hubometer Reading:

Year: 2000

Vehicle Make/Model: ADVANCE TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
		x		Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
		x		Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
		x		Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 12/32 in

Brake(1): No Brake

I/A

Wheel2-On : Tire Tread Depth: 12/32 in

Brake(1): Disc Brake

Min Brake Lining/Pad: 5/8 in • Brake Drum/Rotor: 1.52 in

Wheel3-On : Tire Tread Depth: 12/32 in

Brake(1): Disc Brake

Min Brake Lining/Pad: 1/2 in • Brake Drum/Rotor: 1.5 in

Wheel4 : Tire Tread Depth: 12/32 in

Brake(1): No Brake

I/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 15/32 in

Brake(1): No Brake

I/A

Wheel2-On : Tire Tread Depth: 15/32 in

Brake(1): Disc Brake

Min Brake Lining/Pad: 3/4 in • Brake Drum/Rotor: 1.55 in

Wheel3-On : Tire Tread Depth: 15/32 in

Brake(1): Disc Brake

Min Brake Lining/Pad: 9/16 in • Brake Drum/Rotor: 1.48 in

Wheel4 : Tire Tread Depth: 15/32 in

Brake(1): No Brake

I/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 10/32 in

Brake(1): No Brake

I/A

Wheel4 : Tire Tread Depth: 9/32 in
Brake(1): No Brake
I/A

PASS - vehicle passes inspection

Decal # A237222

Inspection Completed Date: 16Sep2025



Vehicle Standards and Inspection

Jp 7-11

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A237223

Station #: 70215

Station Name: Federated Co-Operatives Limited

Technician #: 90614

Technician Name: Shane Forsythe

Signing Officer #: 83382

Signing Officer Name: Tom Fesciuc

Customer Details:

Name: Federated Coop Limited (Petro)

Address: Box 260, Regina, Saskatchewan, S4P3A1

Inspection Completed Date: 16Sep2025

Inspection Expiry Date: 30Sep2026

Vehicle Details:

VIN: 2AEARUAH0YR000268

Hubometer Reading: 386393 km

Year: 2000

Vehicle Make/Model: ADVANCE TRAILER/

Plate: 575MLP

Jurisdiction: Saskatchewan

Unit: 2813

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70215

Station Name: Federated Co-Operatives Limited

Technician #: 90614

Technician Name: Shane Forsythe

Signing Officer #: 83382

Signing Officer Name: Tom Fesciuc

Customer Details:

Name: Federated Coop Limited (Petro)

Address: Box 260, Regina, Saskatchewan, S4P3A1

Vehicle Details:

VIN: 2AEARUAH0YR000268

Hubometer Reading: 386393 km

Year: 2000

Vehicle Make/Model: ADVANCE TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
		x		Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
		x		Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 10/32 in

Brake(1): No Brake

I/A

Wheel2-On : Tire Tread Depth: 10/32 in

Brake(1): Disc Brake

Min Brake Lining/Pad: 3/8 in • Brake Drum/Rotor: 1.51 in

Wheel3-On : Tire Tread Depth: 12/32 in

Brake(1): Disc Brake

Min Brake Lining/Pad: 11/16 in • Brake Drum/Rotor: 1.57 in

Wheel4 : Tire Tread Depth: 12/32 in

Brake(1): No Brake

I/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 14/32 in

Brake(1): No Brake

I/A

Wheel2-On : Tire Tread Depth: 15/32 in

Brake(1): Disc Brake

Min Brake Lining/Pad: 11/16 in • Brake Drum/Rotor: 1.47 in

Wheel3-On : Tire Tread Depth: 14/32 in

Brake(1): Disc Brake

Min Brake Lining/Pad: 11/16 in • Brake Drum/Rotor: 1.56 in

Wheel4 : Tire Tread Depth: 14/32 in

Brake(1): No Brake

I/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 10/32 in

Brake(1): No Brake

I/A

Wheel4 : Tire Tread Depth: 12/32 in
Brake(1): No Brake
I/A

PASS - vehicle passes inspection

Decal # A237223

Inspection Completed Date: 16Sep2025
