

517-12



Vehicle Standards and Inspection

### Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A262424

Station #: 70400	Station Name: 101076904 Saskatchewan Ltd.
Technician #: 90798	Technician Name: Austin Lasch
Signing Officer #: 89229	Signing Officer Name: Carla Harris

<b>Customer Details:</b>	
Name: Yorkton Concrete Products Ltd (2012)	Address: Box 129, Yorkton, Saskatchewan, S3N 2V6

Inspection Completed Date: 20Apr2026	Inspection Expiry Date: 30Apr2027
--------------------------------------	-----------------------------------

<b>Vehicle Details:</b>	
VIN: 2D9SD352XN1012688	Hubometer Reading:
Year: 2022	Vehicle Make/Model: LOAD LINE TRAILER/TRAILER
Plate: 058 NIC	Jurisdiction: Saskatchewan
Unit: SD-04	

Message(s): VIN has been validated.
-------------------------------------

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.
--



Vehicle Standards and Inspection

### Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70400	Station Name: 101076904 Saskatchewan Ltd.
Technician #: 90798	Technician Name: Austin Lasch
Signing Officer #: 89229	Signing Officer Name: Carla Harris

Customer Details:	
Name: Yorkton Concrete Products Ltd (2012)	Address: Box 129, Yorkton, Saskatchewan, S3N 2V6

Vehicle Details:	
VIN: 2D9SD352XN1012688	Hubometer Reading:
Year: 2022	Vehicle Make/Model: LOAD LINE TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	FRONT RHS CORNER MARKER SCRAPED UP AND PARTIALLY MISSING
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	BOTH GLADHAND RUBBERS WORN OUT
x				Elec Brake System/Components (3.1)	
		x		Wheel Bearings (9)	3RD LHS HUB OIL LEVEL LOW
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

#### Brake/Tire Measurements

##### Axle 1-Pass

Wheel1-On : Tire Tread Depth: 11 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 23/32 in • Cam Rotation: 47.0 degrees • Brake Stroke: 1.75 in

Wheel2 : Tire Tread Depth: 8 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 9 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 6 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 23/32 in • Cam Rotation: 50.0 degrees • Brake Stroke: 1.75 in

##### Axle 2-Pass

Wheel1-On : Tire Tread Depth: 8 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 55.0 degrees • Brake Stroke: 1.75 in

Wheel2 : Tire Tread Depth: 8 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 8 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 9 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21/32 in • Cam Rotation: 64.0 degrees • Brake Stroke: 1.75 in

##### Axle 3-Pass

Wheel1-On : Tire Tread Depth: 15 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 46.0 degrees • Brake Stroke: 1.75 in

Wheel2 : Tire Tread Depth: 13 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 12 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 12 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 72.0 degrees • Brake Stroke: 1.75 in

PASS - vehicle passes inspection

Decal # A262424

Inspection Completed Date: 20Apr2026