



Vehicle Standards and Inspection

J17-14

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A302695

Station #: 70400

Station Name: 101076904 Saskatchewan Ltd.

Technician #: 92588

Technician Name: Kalan Fyck

Signing Officer #: 89229

Signing Officer Name: Carla Harris

Customer Details:

Name: Yorkton Concrete Products Ltd (2012)

Address: Box 129, Yorkton, Saskatchewan, S3N 2V6

Inspection Completed Date: 28May2026

Inspection Expiry Date: 31May2027

Vehicle Details:

VIN: 2MFB2R5D5JR008762

Hubometer Reading:

Year: 2018

Vehicle Make/Model: MIDLAND TRAILER/TRAILER

Plate: 419 NDL

Jurisdiction: Saskatchewan

Unit: SD-03

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70400

Station Name: 101076904 Saskatchewan Ltd.

Technician #: 92588

Technician Name: Kalan Fyck

Signing Officer #: 89229

Signing Officer Name: Carla Harris

Customer Details:

Name: Yorkton Concrete Products Ltd (2012)

Address: Box 129, Yorkton, Saskatchewan, S3N 2V6

Vehicle Details:

VIN: 2MFB2R5D5JR008762

Hubometer Reading:

Year: 2018

Vehicle Make/Model: MIDLAND TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	RHS REAR SIGNAL NOT WORKING
		x		Reflex Reflectors (6)	NO REAR SIDE REFLECTORS
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
		x		Mud Flaps/Fenders (8)	MUDFLAPS AT FRONT OF FRONT FENDER LOOSE, LHS FRONT FENDER HAS TWO LOOSE BOLTS
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	SERVICE GLADHAND RUBBER WORN OUT, ALL HALDEX PIN BUSHINGS WORN OUT
x				Elec Brake System/Components (3.1)	
		x		Wheel Bearings (9)	1ST RHS WHEEL SEAL LEAKING - HUB OIL VERY LOW
		x		Tires/Wheels (9)	2ND LHS INNER TIRE HAS CORDS EXPOSED
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
		x		Suspension/Axles (2)	1ST RHS BOTTOM SHOCK RUBBER PUSHING OUT VERY BAD, 3RD LHS BOTTOM AIR BAG NUT LOOSE
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 12 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 74.0 degrees • Brake Stroke: 1.75 in

Wheel2 : Tire Tread Depth: 11 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 11 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 10 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 25/32 in • Cam Rotation: 40 degrees • Brake Stroke: 1.75 in

Axle 2-Pass

Wheel1-On : Tire Tread Depth: 9 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 45.0 degrees • Brake Stroke: 1.75 in

Wheel2 : Tire Tread Depth: 17 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 12 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 10 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 45.0 degrees • Brake Stroke: 1.75 in

Axle 3-Pass

Wheel1-On : Tire Tread Depth: 9 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15/32 in • Cam Rotation: 108.0 degrees • Brake Stroke: 1.75 in

Wheel2 : Tire Tread Depth: 8 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 7 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 10 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 46.0 degrees • Brake Stroke: 1.75 in

PASS - vehicle passes inspection

Decal # A302695

Inspection Completed Date: 28May2026