



Vehicle Standards and Inspection

## Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A124394

Station #: 71692

Station Name: Shop Box Trailer Repairs Ltd.

Technician #: 85289

Technician Name: David Critchley

Signing Officer #: 90304

Signing Officer Name: Jeanette Britz

H33-9

### Customer Details:

Name: Richards Transport Ltd.

Address: 278 Sherwood Rd., RM of Sherwood, Saskatchewan, S4K0A8

Inspection Completed Date: 06Sep2024

Inspection Expiry Date: 30Sep2025

### Vehicle Details:

VIN: 2LDSD4826V9028215

Hubometer Reading:

Year: 1997

Vehicle Make/Model: LODE KING TRAILER/TRAILER


Plate: 088LVC

Jurisdiction: Saskatchewan

Unit: 20-208

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.





Vehicle Standards and Inspection

## Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71692

Station Name: Shop Box Trailer Repairs Ltd.

Technician #: 85289

Technician Name: David Critchley

Signing Officer #: 90304

Signing Officer Name: Jeanette Britz

### Customer Details:

Name: Richards Transport Ltd.

Address: 278 Sherwood Rd., RM of Sherwood, Saskatchewan, S4K0A8

### Vehicle Details:

VIN: 2LDSD4826V9028215

Hubometer Reading:

Year: 1997

Vehicle Make/Model: LODE KING TRAILER TRAILER

### Inspection Details:

| Pass | Rejected | Corrected | Req Attn | DRIVERS COMPARTMENT          | Comments |
|------|----------|-----------|----------|------------------------------|----------|
| x    |          |           |          | Vehicle Identification (5)   |          |
| x    |          |           |          | Fire Extinguisher (5)        |          |
| x    |          |           |          | Auxiliary Controls/Equip (5) |          |

| Pass | Rejected | Corrected | Req Attn | BODY EXTERIOR                 | Comments |
|------|----------|-----------|----------|-------------------------------|----------|
| x    |          |           |          | Lamps (6)                     |          |
| x    |          |           |          | Reflex Reflectors (6)         |          |
| x    |          |           |          | Retro Reflective Markings (6) |          |
| x    |          |           |          | Trailer Hitch (10)            |          |
| x    |          |           |          | Attached Equipment (8)        |          |
| x    |          |           |          | Cargo Bodies/Vessels (8)      |          |
| x    |          |           |          | Mud Flaps/Fenders (8)         |          |
| x    |          |           |          | Landing Gear (8)              |          |
| x    |          |           |          | Rear Impact Guard (8)         |          |
| x    |          |           |          | Trailer Power Cord (7)        |          |

| Pass | Rejected | Corrected | Req Attn | ENGINE COMPARTMENT           | Comments |
|------|----------|-----------|----------|------------------------------|----------|
| x    |          |           |          | Fuel System (1)              |          |
| x    |          |           |          | Battery/Wiring Condition (7) |          |

| Pass | Rejected | Corrected | Req Attn | CHASSIS                                 | Comments                      |
|------|----------|-----------|----------|-----------------------------------------|-------------------------------|
| x    |          |           |          | Hyd Brake System/Components (3.1)       |                               |
|      |          |           | x        | Air Brake System/Components (3.2)       | Replaced right front maxipot. |
| x    |          |           |          | Elec Brake System/Components (3.1)      |                               |
| x    |          |           |          | Wheel Bearings (9)                      |                               |
| x    |          |           |          | Tires/Wheels (9)                        |                               |
| x    |          |           |          | Self-Steering Axle (2&4)                |                               |
| x    |          |           |          | Frame/Crossmembers/Mounts (8)           |                               |
|      |          |           | x        | Suspension/Axles (2)                    | Replaced all shocks.          |
| x    |          |           |          | Exhaust/Emission System (1)             |                               |
| x    |          |           |          | Sliding Axle Assembly (if equipped) (8) |                               |

#### Brake/Tire Measurements

##### Axle 1-Pass

Wheel1 : Tire Tread Depth: NA in

Brake(1): No Brake

N/A

Wheel2 : Tire Tread Depth: NA in

Brake(1): No Brake

N/A

##### Axle 2-Pass

Wheel1-On : Tire Tread Depth: 14 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 55 degrees • Brake Stroke: 1 1/2 in

Wheel2-On : Tire Tread Depth: 14 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 55 degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 18 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 45 degrees • Brake Stroke: 1 1/2 in

Wheel4-On : Tire Tread Depth: 18 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 45 degrees • Brake Stroke: 1 1/2 in

##### Axle 3-Pass

Wheel1-On : Tire Tread Depth: 16 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 50 degrees • Brake Stroke: 1 1/2 in

Wheel2-On : Tire Tread Depth: 17 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 50 degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 13 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 85 degrees • Brake Stroke: 1 1/2 in

Wheel4-On : Tire Tread Depth: 12 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 85 degrees • Brake Stroke: 1 1/2 in

PASS - vehicle passes inspection

Decal # A124394

Inspection Completed Date: 06Sep2024