



Vehicle Standards and Inspection

P33-1

SOS-2

## Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A98052

275

Station #: 71786

Station Name: Penny's Pit Stop Ltd.

Technician #: 81313

Technician Name: Gary Penny

Signing Officer #: 90385

Signing Officer Name: Jamie Penny

### Customer Details:

Name: Pro-lift Cranes Services Ltd.

Address: Box 2759, Lloydminster, Saskatchewan, S9V 0Z1

Inspection Completed Date: 13Nov2024

Inspection Expiry Date: 30Nov2025

### Vehicle Details:

VIN: 4UGFG4038PD040244

Hubometer Reading:

Year: 2023

Vehicle Make/Model: SWS TRAILER/TRAILER

Plate: 384 NEE

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.





Vehicle Standards and Inspection

## Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71786

Station Name: Penny's Pit Stop Ltd.

Technician #: 81313

Technician Name: Gary Penny

Signing Officer #: 90385

Signing Officer Name: Jamie Penny

### Customer Details:

Name: Pro-lift Cranes Services Ltd.

Address: Box 2759, Lloydminster, Saskatchewan, S9V 0Z1

### Vehicle Details:

VIN: 4UGFG4038PD040244

Hubometer Reading:

Year: 2023

Vehicle Make/Model: SWS TRAILER TRAILER

### Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
x				Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (If equipped) (8)	

#### Brake/Tire Measurements

##### Axle 1-Pass

Wheel1 : Tire Tread Depth: 9/32 in

Brake(1): No Brake

N/A

Wheel2-Off : Tire Tread Depth: 9/32 in

Brake(1): Drum Brake

• Min Brake Lining/Pad: 6/32 in • Brake Drum/Rotor: 312.20 mm

Wheel3-Off : Tire Tread Depth: 3/32 in

Brake(1): Drum Brake

• Min Brake Lining/Pad: 4/32 in • Brake Drum/Rotor: 312.14 mm

Wheel4 : Tire Tread Depth: 5/32 in

Brake(1): No Brake

N/A

##### Axle 2-Pass

Wheel1 : Tire Tread Depth: 5/32 in

Brake(1): No Brake

N/A

Wheel2-Off : Tire Tread Depth: 5/32 in

Brake(1): Drum Brake

• Min Brake Lining/Pad: 8/32 in • Brake Drum/Rotor: 312.17 mm

Wheel3-Off : Tire Tread Depth: 9/32 in

Brake(1): Drum Brake

• Min Brake Lining/Pad: 3/32 in • Brake Drum/Rotor: 312.18 mm

Wheel4 : Tire Tread Depth: 9/32 in

Brake(1): No Brake

N/A

##### Axle 3-Pass

Wheel1 : Tire Tread Depth: 3/32 in

Brake(1): No Brake

N/A

Wheel2-Off : Tire Tread Depth: 4/32 in

Brake(1): Drum Brake

• Min Brake Lining/Pad: 6/32 in • Brake Drum/Rotor: 312.12 mm

Wheel3-Off : Tire Tread Depth: 6/32 in

Brake(1): Drum Brake

• Min Brake Lining/Pad: 3/32 in • Brake Drum/Rotor: 312.16 mm

Wheel4 : Tire Tread Depth: 4/32 in  
Brake(1): No Brake  
N/A

PASS - vehicle passes inspection

Decal # A98052

Inspection Completed Date: 13Nov2024

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km.  
Failure to do so may result in damage or serious injury.