



Vehicle Standards and Inspection

Heavy Truck Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A308991

533-1

Station #: 71760

Station Name: CDR Welding & Inspections Ltd.

Technician #: 91774

Technician Name: Gregory Charabin

Signing Officer #: 90280

Signing Officer Name: Devin Flalkowski

Customer Details:

Name: Onion Lake Cree Nation Well Servicing GFAAddress: Box 606, Onion Lake, Saskatchewan, S0M2E0

Inspection Completed Date: 23Apr2025

Inspection Expiry Date: 30Apr2026

Vehicle Details:

VIN: 1HTMMAAN03H565010

Odometer Reading: 129409 km

Year: 2003

Vehicle Make/Model: INTERNATIONAL/HEAVY VEHICLE

Plate: 192IXK

Jurisdiction: Saskatchewan

Unit: 2351

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Heavy Truck Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71760

Station Name: CDR Welding & Inspections Ltd.

Technician #: 91774

Technician Name: Gregory Charabin

Signing Officer #: 90280

Signing Officer Name: Davin Flakowski

Customer Details:

Name: Onion Lake Cree Nation Well Servicing GP

Address: Box 606, Onion Lake, Saskatchewan, S0M2E0

Vehicle Details:

VIN: 1HTMMAAN03H565010

Odometer Reading: 129409 km

Year: 2003

Vehicle Make/Model: INTERNATIONAL HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 9 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 mm • Cam Rotation: 55 degrees • Brake Stroke: 30 mm

Wheel2-On : Tire Tread Depth: 9 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 17 mm • Cam Rotation: 42 degrees • Brake Stroke: 30 mm

Axle 2-Pass

Wheel1 : Tire Tread Depth: 15 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 15 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 mm • Cam Rotation: 45 degrees • Brake Stroke: 38 mm

Wheel3-On : Tire Tread Depth: 15 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 mm • Cam Rotation: 48 degrees • Brake Stroke: 38 mm

Wheel4 : Tire Tread Depth: 15 mm

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A308991

Inspection Completed Date: 23Apr2025