



Vehicle Standards and Inspection

H30-2

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # P245457

Station #: 70740

Station Name: Sydia Bros Ent Ltd

Technician #: 90834

Technician Name: Ian Homburg

Signing Officer #: 91568

Signing Officer Name: Erica Durocher

Customer Details:

Name: Sydia Bros Ent Ltd

Address: PO Box 2477 Stn Main, Lloydminster, Saskatchewan, S9V 1W5

Inspection Completed Date: 28Nov2024

Inspection Expiry Date: 30Nov2025

Vehicle Details:

VIN: 2A9LB5531MS037037

Hubometer Reading:

Year: 1991

Vehicle Make/Model: ASPEN TRAILER/ASPEN

Plate: 368MER

Jurisdiction: Saskatchewan

Unit: 360D

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70740

Station Name: Sydia Bros Ent Ltd

Technician #: 90834

Technician Name: Ian Homburg

Signing Officer #: 91568

Signing Officer Name: Erica Durocher

Customer Details:

Name: Sydia Bros Ent Ltd

Address: PO Box 2477 Strn Main, Lloydminster, Saskatchewan, S9V

Vehicle Details:

VIN: 2A9LB5531MS037037

Hubometer Reading:

Year: 1991

Vehicle Make/Model: ASPEN TRAILER ASPEN

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	replace neck glad hands
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
		x		Tires/Wheels (9)	replace right front outside tire valve stem, replace eft middle brake backing plate
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 17 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 19 mm • Cam Rotation: 45.0 degrees • Brake Stroke: 1 1/4 in

Wheel2-On : Tire Tread Depth: 17 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 19 mm • Cam Rotation: 45.0 degrees • Brake Stroke: 1 1/4 in

Wheel3-On : Tire Tread Depth: 16 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 75.0 degrees • Brake Stroke: 1 1/4 in

Wheel4-On : Tire Tread Depth: 13 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 75.0 degrees • Brake Stroke: 1 1/4 in

Axle 2-Pass

Wheel1-On : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 75.0 degrees • Brake Stroke: 1 1/4 in

Wheel2-On : Tire Tread Depth: 15 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 75.0 degrees • Brake Stroke: 1 1/4 in

Wheel3-On : Tire Tread Depth: 13 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 17 mm • Cam Rotation: 60.0 degrees • Brake Stroke: 1 1/4 in

Wheel4-On : Tire Tread Depth: 13 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 17 mm • Cam Rotation: 60.0 degrees • Brake Stroke: 1 1/4 in

Axle 3-Pass

Wheel1-On : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 75.0 degrees • Brake Stroke: 1 1/4 in

Wheel2-On : Tire Tread Depth: 13 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 75.0 degrees • Brake Stroke: 1 1/4 in

Wheel3-On : Tire Tread Depth: 13 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 75.0 degrees • Brake Stroke: 1 1/4 in

Wheel4-On : Tire Tread Depth: 12 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 75.0 degrees • Brake Stroke: 1 1/4 in

PASS - vehicle passes inspection

Decal # P245457

Inspection Completed Date: 28Nov2024