



Vehicle Standards and Inspection

C40.12 #31-2

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A258464

Station #: 70207	Station Name: Frontline Truck & Trailer
Technician #: 84329	Technician Name: Ben Blythe
Signing Officer #: 90414	Signing Officer Name: Howard Thomson

Customer Details:	
Name: Loneridge Services LTD.	Address: Box 22002 RPO Wildwood, Saskatoon, Saskatchewan, S7H 5P1

Inspection Completed Date: 10Mar2026	Inspection Expiry Date: 31Mar2027
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 2G9LS43T7MB105181	Hubometer Reading:
Year: 2021	Vehicle Make/Model: GINCOR/TRAILER
Plate: 439 MVI	Jurisdiction: Saskatchewan
Unit: LB05	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.