

E30-2



Vehicle Standards and Inspection

Heavy Truck Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A298620

Station #: 71589	Station Name: Automotive Unlimited
Technician #: 91407	Technician Name: Jordan McNeil
Signing Officer #: 91038	Signing Officer Name: Amanda Andres

Customer Details:

Name: Southern Pressure Testers ltd	Address: box 26, gull lake, Saskatchewan, s0w1a0
-------------------------------------	--

Inspection Completed Date: 13Apr2026	Inspection Expiry Date: 30Apr2027
--------------------------------------	-----------------------------------

Vehicle Details:

VIN: 1FVDC2CS07HX29701	Odometer Reading: 42268 km
Year: 2007	Vehicle Make/Model: FREIGHTLINER/HEAVY VEHICLE
Plate: 457JYQ	Jurisdiction: Saskatchewan
Unit: 42	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Heavy Truck Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71589

Station Name: Automotive Unlimited

Technician #: 91407

Technician Name: Jordan McNeil

Signing Officer #: 91038

Signing Officer Name: Amanda Andres

Customer Details:

Name: Southern Pressure Testers ltd

Address: box 26, gull lake, Saskatchewan, s0w1a0

Vehicle Details:

VIN: 1FVDC2CS07HX29701

Odometer Reading: 42268 km

Year: 2007

Vehicle Make/Model: FREIGHTLINER HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxillary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	

x				Air Brake System/Components (3.2)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 20/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 in • Cam Rotation: 60 degrees • Brake Stroke: 1 3/4 in

Wheel2-On : Tire Tread Depth: 21/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 in • Cam Rotation: 60 degrees • Brake Stroke: 1 3/4 in

Axle 2-Pass

Wheel1 : Tire Tread Depth: 15/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 21/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 20 mm • Cam Rotation: 40 degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 5/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 20 mm • Cam Rotation: 40 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 19/32 in

Brake(1): No Brake

N/A

PASS - vehicle passes inspection	Decal # A298620	Inspection Completed Date: 13Apr2026
----------------------------------	-----------------	--------------------------------------