



Vehicle Standards and Inspection

X48-2

### Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A215838

Station #: 70083	Station Name: TPZ Services Ltd
Technician #: 91991	Technician Name: Brady Court
Signing Officer #: 86277	Signing Officer Name: Kari Blatchford

Customer Details:	
Name: Integrity Maintenance Ltd	Address: PO Box 725, Carlyle, Saskatchewan, S0C 0R0

Inspection Completed Date: 08Dec2025	Inspection Expiry Date: 31Dec2026
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 2N9LB4038CE065298	Hubometer Reading:
Year: 2012	Vehicle Make/Model: TRAILER/TRAILER
Plate: 429LTX	Jurisdiction: Saskatchewan
Unit: 429LTX	

Message(s): VIN has been validated.
-------------------------------------

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

### Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70083

Station Name: TPZ Services Ltd

Technician #: 91991

Technician Name: Brady Court

Signing Officer #: 86277

Signing Officer Name: Kari Blatchford

**Customer Details:**

Name: Integrity Maintenance Ltd

Address: PO Box 725, Carlyle, Saskatchewan, S0C 0R0

**Vehicle Details:**

VIN: 2N9LB4038CE065298

Hubometer Reading:

Year: 2012

Vehicle Make/Model: TRAILER TRAILER

**Inspection Details:**

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	License plate light, side light
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
		x		Cargo Bodies/Vessels (8)	replace broken boards
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	brake drums, brake pads, 3 s-cam on passenger side
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
		x		Suspension/Axles (2)	weld axle limit chains
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

**Brake/Tire Measurements**

**Axle 1-Pass**

Wheel1-On : Tire Tread Depth: 12 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 22.8 mm • Cam Rotation: 16.0 degrees • Brake Stroke: 62 mm

Wheel2 : Tire Tread Depth: 12 mm

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 8 mm

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 7 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 22.8 mm • Cam Rotation: 18.0 degrees • Brake Stroke: 64 mm

**Axle 2-Pass**

Wheel1-On : Tire Tread Depth: 17 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 22.8 mm • Cam Rotation: 15.0 degrees • Brake Stroke: 55 mm

Wheel2 : Tire Tread Depth: 17 mm

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 9 mm

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 12 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 22.8 mm • Cam Rotation: 20.0 degrees • Brake Stroke: 60 mm

**Axle 3-Pass**

Wheel1-On : Tire Tread Depth: 10 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 22.8 mm • Cam Rotation: 15.0 degrees • Brake Stroke: 62 mm

Wheel2 : Tire Tread Depth: 10 mm

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 17 mm

Brake(1): No Brake

N/A

• Wheel-On : Tire Tread Depth: 17 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 22.8 mm • Cam Rotation: 30.0 degrees • Brake Stroke: 63 mm

PASS - vehicle passes inspection

Decal # A215838

Inspection Completed Date: 08Dec2025