



Vehicle Standards and Inspection

COPY

J17-1

### Heavy Truck Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A212821

Station #: 70400	Station Name: 101076904 Saskatchewan Ltd.
Technician #: 90798	Technician Name: Austin Lasch
Signing Officer #: 89229	Signing Officer Name: Carla Harris

Customer Details:

Name: Yorkton Concrete Products Ltd (2012)      Address: Box 129, Yorkton, Saskatchewan, S3N 2V6

Inspection Completed Date: 09Jan2026      Inspection Expiry Date: 31Jan2027

Vehicle Details:

VIN: 2NPRLZ0XX7M733503	Odometer Reading: 195072 km
Year: 2007	Vehicle Make/Model: PETERBILT/HEAVY VEHICLE
Plate: 905 NQE	Jurisdiction: Saskatchewan
Unit: 3	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

## Heavy Truck Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70400

Station Name: 101076904 Saskatchewan Ltd.

Technician #: 90798

Technician Name: Austin Lasch

Signing Officer #: 89229

Signing Officer Name: Carla Harris

**Customer Details:**

Name: Yorkton Concrete Products Ltd (2012)

Address: Box 129, Yorkton, Saskatchewan, S3N 2V6

**Vehicle Details:**

VIN: 2NPRLZ0XX7M733503

Odometer Reading: 195072 km

Year: 2007

Vehicle Make/Model: PETERBILT HEAVY VEHICLE

**Inspection Details:**

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
		x		Clutch/Clutch Pedal (1)	CLUTCH NEEDS ADJUSTMENT

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Headlamp Aim (6)	
		x		Reflex Reflectors (6)	LHS MUDFLAP REFLECTIVE BAR WORN OUT
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
		x		Cab/Hood Safety Catches (8)	HOOD BUSHINGS WORN OUT
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
------	----------	-----------	----------	---------	----------

x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	3RD LHS BRAKE SHOES RUNNING OUT OF DRUM
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
		x		Exhaust/Emission System (1)	EXHAUST CLAMP UNDER CAB RUSTED OUT

**Brake/Tire Measurements**

**Axle 1-Pass**

Wheel1-On : Tire Tread Depth: 21 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21/32 in • Cam Rotation: 65.0 degrees • Brake Stroke: 1.75 in

Wheel2-On : Tire Tread Depth: 22 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21/32 in • Cam Rotation: 65.0 degrees • Brake Stroke: 1.75 in

**Axle 2-Pass**

Wheel1-On : Tire Tread Depth: 19 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 70.0 degrees • Brake Stroke: 1.75 mm

Wheel2 : Tire Tread Depth: 21 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 19 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 20 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 45.0 degrees • Brake Stroke: 1.75 in

**Axle 3-Pass**

Wheel1-On : Tire Tread Depth: 25 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 35.0 degrees • Brake Stroke: 1.75 in

Wheel2 : Tire Tread Depth: 26 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 27 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 27 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 45.0 degrees • Brake Stroke: 1.75 in

PASS - vehicle passes inspection

Decal # A212821

Inspection Completed Date: 09Jan2026