



Vehicle Standards and Inspection

COPY

J17-3

Heavy Truck Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A318450

Station #: 70400

Station Name: 101076904 Saskatchewan Ltd.

Technician #: 90798

Technician Name: Austin Lasch

Signing Officer #: 89229

Signing Officer Name: Carla Harris

Customer Details:

Name: Yorkton Concrete Products Ltd (2012) Address: Box 129, Yorkton, Saskatchewan, S3N 2V6

Inspection Completed Date: 02Jul2025

Inspection Expiry Date: 31Jul2026

Vehicle Details:

VIN: 1FDZS96T4WVA08911

Odometer Reading: 452517 km

Year: 1998

Vehicle Make/Model: FORD/HEAVY VEHICLE

Plate: 902 NQE

Jurisdiction: Saskatchewan

Unit: 13

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Heavy Truck Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70400

Station Name: 101076904 Saskatchewan Ltd.

Technician #: 90798

Technician Name: Austin Lasch

Signing Officer #: 89229

Signing Officer Name: Carla Harris

Customer Details:

Name: Yorkton Concrete Products Ltd (2012)

Address: Box 129, Yorkton, Saskatchewan, S3N 2V6

Vehicle Details:

VIN: 1FDZS96T4WVA08911

Odometer Reading: 452517 km

Year: 1998

Vehicle Make/Model: FORD HEAVY VEHICLE

Inspection Details:

| Pass | Rejected | Corrected | Req Attn | DRIVERS COMPARTMENT | Comments |
|------|----------|-----------|----------|--|-------------------------|
| x | | | | Vehicle Identification (5) | |
| x | | | | Sun Visor Interior (8) | |
| x | | | | Horn Operation (5) | |
| x | | | | Mirrors (8) | |
| | | x | | Windshield Wipers/Washers (8) | LHS WIPER TORN |
| x | | | | Windshield Defroster/Heater (8) | |
| | | x | | Windshield/Other Glass (8) | WINDSHIELD CRACKED |
| x | | | | Gear Position Indicator & Neutral Switch (1) | |
| x | | | | Instrument Lamps (6) | |
| x | | | | Accessibility Features/Equip (5) | |
| x | | | | Auxiliary Heaters (5) | |
| x | | | | Auxiliary Drive Controls (5) | |
| x | | | | Emergency Exits (8) | |
| x | | | | Floor/Step Well Covering (8) | |
| x | | | | Service/Exit Doors (8) | |
| x | | | | Indicator Lamps (5) | |
| x | | | | Instruments/Gauges (5) | |
| x | | | | Switches (7) | |
| x | | | | Brake Pedal/Actuator (3) | |
| | | x | | Clutch/Clutch Pedal (1) | CLUTCH NEEDS ADJUSTMENT |

| | | | | | |
|---|--|---|--|----------------------------------|-----------------------------|
| x | | | | Fire Extinguisher/Hazard Kit (5) | |
| x | | | | Seats/Seat Belts/SRS (8) | |
| | | x | | Steering Column/Components (4) | BOTH TIE ROD ENDS HAVE PLAY |
| x | | | | Auxiliary Controls/Equip (5) | |
| x | | | | Speedometer/Odometer (5) | |
| x | | | | Steering Lash/Travel (5) | |
| x | | | | Accelerator Pedal/Actuator (1) | |
| x | | | | Engine Shut Down Control (1) | |
| x | | | | Engine Start Feature (1) | |
| x | | | | Body Interior/Fixtures (8) | |

| Pass | Rejected | Corrected | Req Attn | BODY EXTERIOR | Comments |
|------|----------|-----------|----------|----------------------------------|--|
| | | x | | Lamps (6) | RHS REAR OUTER TAILLIGHT DIM, LHS REAR INNER TAILLIGHT MARKER NOT WORKING, PLATE LIGHT OUT, DAYTIME RUNNING LIGHTS NOT WORKING |
| x | | | | Headlamp Aim (6) | |
| x | | | | Reflex Reflectors (6) | |
| x | | | | Retro Reflective Markings (6) | |
| x | | | | Body/Bumpers (8) | |
| x | | | | Trailer Hitch (10) | |
| | | x | | Cab Grab Handles/Steps (8) | BOTH DRIVER/PASSENGER BOTTOM STEPS LOOSE |
| x | | | | Attached Equipment (8) | |
| x | | | | Cargo Bodies/Vessels (8) | |
| x | | | | Sun Visor Exterior (8) | |
| x | | | | Mud Flaps/Fenders (8) | |
| x | | | | Trailer Power Cord (7) | |
| x | | | | Chain/Headache Rack (5) | |
| x | | | | Auxiliary Compartments (8) | |
| x | | | | Hybrid Vehicle Drive Systems (1) | |
| x | | | | Unitized Body Elements (8) | |

| Pass | Rejected | Corrected | Req Attn | ENGINE COMPARTMENT | Comments |
|------|----------|-----------|----------|------------------------------|-----------------------|
| x | | | | Cab/Hood Safety Catches (8) | |
| x | | | | Power Steering System (4) | |
| x | | | | Fuel System (1) | |
| x | | | | Battery/Wiring Condition (7) | |
| | | x | | Air Suspended Cab (8) | LHS CAB SHOCK LEAKING |
| x | | | | Cab Mounts (8) | |
| x | | | | Drive Belts (1) | |

| Pass | Rejected | Corrected | Req Attn | CHASSIS | Comments |
|------|----------|-----------|----------|-----------------------------------|--|
| x | | | | Hyd Brake System/Components (3.1) | |
| | | x | | Air Brake System/Components (3.2) | 2ND LHS JAM NUT LOOSE |
| x | | | | Wheel Bearings (9) | |
| x | | | | King Pins/Ball Joints (4) | |
| x | | | | Steering Linkage (4) | |
| x | | | | Tires/Wheels (9) | |
| x | | | | Self-Steering Axle (4) | |
| x | | | | Engine/Transmission Mounts (1) | |
| x | | | | Frame/Crossmembers/Mounts (8) | |
| x | | | | Suspension/Axles (2) | |
| x | | | | Drive Shaft/Universal Joints (1) | |
| | | x | | Exhaust/Emission System (1) | STEP CLAMP AT FLEX PIPE ROUTED TO TURBO LEAKING |

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 18 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 35.0 degrees • Brake Stroke: 1.75 in

Wheel2-On : Tire Tread Depth: 18 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 35.0 degrees • Brake Stroke: 1.75 in

Axle 2-Pass

Wheel1-On : Tire Tread Depth: 9 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 65.0 degrees • Brake Stroke: 1.75 in

Wheel2 : Tire Tread Depth: 12 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 7 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 13 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 23/32 in • Cam Rotation: 55.0 degrees • Brake Stroke: 1.75 in

Axle 3-Pass

Wheel1-On : Tire Tread Depth: 13 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15/32 in • Cam Rotation: 112.0 degrees • Brake Stroke: 1.75 in

Wheel2 : Tire Tread Depth: 13 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 11 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 12 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 23/32 in • Cam Rotation: 55.0 degrees • Brake Stroke: 1.75 in

PASS - vehicle passes inspection

Decal # A318450

Inspection Completed Date: 02Jul2025