



Vehicle Standards and Inspection

5 17-b

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A302688

Station #: 70400	Station Name: 101076904 Saskatchewan Ltd.
Technician #: 89698	Technician Name: Bryden Dubiel
Signing Officer #: 85971	Signing Officer Name: Eileen Fyck

Customer Details:	
Name: Yorkton Concrete Products Ltd (2012)	Address: Box 129, Yorkton, Saskatchewan, S3N 2V6

Inspection Completed Date: 22May2026	Inspection Expiry Date: 31May2027
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 2S9NE3692L1041535	Hubometer Reading:
Year: 2020	Vehicle Make/Model: RENN/TRAILER
Plate: 404 LUB	Jurisdiction: Saskatchewan
Unit:	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70400

Station Name: 101076904 Saskatchewan Ltd.

Technician #: 89698

Technician Name: Bryden Dubiel

Signing Officer #: 85971

Signing Officer Name: Eileen Fyck

Customer Details:

Name: Yorkton Concrete Products Ltd (2012)

Address: Box 129, Yorkton, Saskatchewan, S3N 2V6

Vehicle Details:

VIN: 2S9NE3692L1041535

Hubometer Reading:

Year: 2020

Vehicle Make/Model: RENN TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
		x		Vehicle Identification (5)	CAN NOT READ VIN PLATE
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	FRONT RIGHT MARKER OUT, LEFT REAR MARKER VERY DIM
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
x				Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 15 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 56.0 degrees • Brake Stroke: 1.75 in

Wheel2 : Tire Tread Depth: 14 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 16 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 16 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 58.0 degrees • Brake Stroke: 1.75 in

Axle 2-Pass

Wheel1-On : Tire Tread Depth: 18 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 60.0 degrees • Brake Stroke: 1.75 in

Wheel2 : Tire Tread Depth: 18 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 17 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 17 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 61.0 degrees • Brake Stroke: 1.75 in

Axle 3-Pass

Wheel1-On : Tire Tread Depth: 16 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 59.0 degrees • Brake Stroke: 1.75 in

Wheel2 : Tire Tread Depth: 15 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 14 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 14 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21/32 in • Cam Rotation: 64.0 degrees • Brake Stroke: 1.75 in

PASS - vehicle passes inspection

Decal # A302688

Inspection Completed Date: 22May2026