



Vehicle Standards and Inspection

517-7

### Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A262431

Station #: 70400

Station Name: 101076904 Saskatchewan Ltd.

Technician #: 88263

Technician Name: Bryce Fisher

Signing Officer #: 89229

Signing Officer Name: Carla Harris

**Customer Details:**

Name: Yorkton Concrete Products Ltd (2012)      Address: Box 129, Yorkton, Saskatchewan, S3N 2V6

Inspection Completed Date: 21Apr2026

Inspection Expiry Date: 31Oct2026

**Vehicle Details:**

VIN: 5KJJBWDR8SLWC0024

Odometer Reading: 61141 km

Year: 2025

Vehicle Make/Model: WESTERN STAR/HEAVY VEHICLE

Plate: 049 NUE

Jurisdiction: Saskatchewan

Unit: SU-02

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

# Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70400

Station Name: 101076904 Saskatchewan Ltd.

Technician #: 88263

Technician Name: Bryce Fisher

Signing Officer #: 89229

Signing Officer Name: Carla Harris

### Customer Details:

Name: Yorkton Concrete Products Ltd (2012)

Address: Box 129, Yorkton, Saskatchewan, S3N 2V6

### Vehicle Details:

VIN: 5KJJBWDR8SLWC0024

Odometer Reading: 61141 km

Year: 2025

Vehicle Make/Model: WESTERN STAR HEAVY VEHICLE

### Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	

x				Air Brake System/Components (3.2)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
		x		Tires/Wheels (9)	3RD RHS OUTER TIRE LOW ON AIR
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	

**Brake/Tire Measurements**

**Axle 1-Pass**

Wheel1-On : Tire Tread Depth: 14 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 27/32 in • Cam Rotation: 25.0 degrees • Brake Stroke: 2.0 in

Wheel2-On : Tire Tread Depth: 12 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 27/32 in • Cam Rotation: 25.0 degrees • Brake Stroke: 2.0 in

**Axle 2-Pass**

Wheel1-On : Tire Tread Depth: 17 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 27.0 degrees • Brake Stroke: 2.0 in

Wheel2 : Tire Tread Depth: 18 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 16 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 15 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 29.0 degrees • Brake Stroke: 2.0 in

**Axle 3-Pass**

Wheel1-On : Tire Tread Depth: 14 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 28.0 degrees • Brake Stroke: 2.0 in

Wheel2 : Tire Tread Depth: 14 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 14 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 15 in

Brake(1): S-CAM Brake

Min Brake Lining/Pad: 13/16 in • Cam Rotation: 29.0 degrees • Brake Stroke: 2.0 in

PASS - vehicle passes inspection

Decal # A262431

Inspection Completed Date: 21Apr2026