

317-8



Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A262410

Station #: 70400	Station Name: 101076904 Saskatchewan Ltd.
Technician #: 88263	Technician Name: Bryce Fisher
Signing Officer #: 89229	Signing Officer Name: Carla Harris

Customer Details:	
Name: Yorkton Concrete Products Ltd (2012)	Address: Box 129, Yorkton, Saskatchewan, S3N 2V6

Inspection Completed Date: 13Apr2026	Inspection Expiry Date: 31Oct2026
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 3AKJGND16EDFS6059	Odometer Reading: 432642 km
Year: 2014	Vehicle Make/Model: FREIGHTLINER/HEAVY VEHICLE
Plate: 181 MYZ	Jurisdiction: Saskatchewan
Unit: SU-04	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70400

Station Name: 101076904 Saskatchewan Ltd.

Technician #: 88263

Technician Name: Bryce Fisher

Signing Officer #: 89229

Signing Officer Name: Carla Harris

Customer Details:

Name: Yorkton Concrete Products Ltd (2012)

Address: Box 129, Yorkton, Saskatchewan, S3N 2V6

Vehicle Details:

VIN: 3AKJGND16EDFS6059

Odometer Reading: 432642 km

Year: 2014

Vehicle Make/Model: FREIGHTLINER HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
		x		Windshield Wipers/Washers (8)	RHS WINDSHIELD WIPER WORN OUT
x				Windshield Defroster/Heater (8)	
		x		Windshield/Other Glass (8)	LHS WINDOW DOESN'T ROLL DOWN, RHS WINDSHIELD CRACKED
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	

x				Clutch/Clutch Pedal (1)	
x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	RHS SIGNALS NOT WORKING
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
		x		Trailer Hitch (10)	5TH WHEEL NEEDS ADJUSTMENT, ONE OF THE FRONT & ONE OF THE REAR 5TH WHEEL CROSS BAR PINS LOOSE
		x		Cab Grab Handles/Steps (8)	LHS TOP STEP UNDER DOOR LOOSE, LHS BOTTOM STEP ON FUEL TANK LOOSE
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
		x		Mud Flaps/Fenders (8)	RHS MUDFLAP MISSING
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
x				Air Brake System/Components (3.2)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
		x		Suspension/Axles (2)	ALL FOUR SPRING EYE BUSHINGS HAVE PLAY
		x		Drive Shaft/Universal Joints (1)	2ND OUTPUT YOKE LOOSE, 3RD INPUT U-JOINT VERY WORN OUT
		x		Exhaust/Emission System (1)	LHS STACK HEAT SHIELD CLAMP AT TOP BROKEN, LHS EXHAUST MOUNT BRACKET BROKEN OFF BY FRAME RAIL

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 10 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 44.0 degrees • Brake Stroke: 2.0 in

Wheel2-On : Tire Tread Depth: 11 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 41.0 degrees • Brake Stroke: 2.0 in

Axle 2-Pass

Wheel1-On : Tire Tread Depth: 14 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 36.0 degrees • Brake Stroke: 2.0 in

Wheel2 : Tire Tread Depth: 13 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 13 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 12 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 38.0 degrees • Brake Stroke: 2.0 in

Axle 3-Pass

Wheel1-On : Tire Tread Depth: 25 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 42.0 degrees • Brake Stroke: 2.0 in

Wheel2 : Tire Tread Depth: 25 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 26 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 24 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 43.0 degrees • Brake Stroke: 2.0 in

PASS - vehicle passes inspection

Decal # A262410

Inspection Completed Date: 13Apr2026