



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # P276523

P276523

Station #: 71131

Station Name: TKC Trucking and Picker Service

Technician #: 90508

Technician Name: Derrick Ching

Signing Officer #: 85781

Signing Officer Name: Troy Ching

Customer Details:

Name: **TKC Trucking and Picker Service Ltd.**

Address: Box 2337, Kindersley, Saskatchewan, S0L 1S0

Inspection Completed Date: 17Jul2026

Inspection **Expiry Date: 31Jul2027**

Vehicle Details:

VIN: 2A9LB4035CN125042

Hubometer Reading: 15903 km

Year: 2012

Vehicle Make/Model: ASPEN TRAILER/ASPEN

Plate: 65J352

Jurisdiction: Alberta

Unit: TL17

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.

For - 3



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71131 Station Name: TKC Trucking and Picker Service
Technician #: 90508 Technician Name: Derrick Ching
Signing Officer #: 85781 Signing Officer Name: Troy Ching

Customer Details:

Name: TKC Trucking and Picker Service Ltd. Address: Box 2337, Kindersley, Saskatchewan, S0L 1S0

Vehicle Details:

VIN: 2A9LB4035CN125042 Hubometer Reading: 15903 km
Year: 2012 Vehicle Make/Model: ASPEN TRAILER ASPEN

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
x				Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 8 in
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 30 degrees • Brake Stroke: 1.5 in
Wheel2 : Tire Tread Depth: 8 in
Brake(1): No Brake
N/A
Wheel3-On : Tire Tread Depth: 22 in
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 30 degrees • Brake Stroke: 1.5 in
Wheel4 : Tire Tread Depth: 22 in
Brake(1): No Brake
N/A

Axle 2-Pass

Wheel1-On : Tire Tread Depth: 18 in
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 30 degrees • Brake Stroke: 1.5 in
Wheel2 : Tire Tread Depth: 10 in
Brake(1): No Brake
N/A
Wheel3-On : Tire Tread Depth: 15 in
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 30 degrees • Brake Stroke: 1.5 in
Wheel4 : Tire Tread Depth: 15 in
Brake(1): No Brake
N/A

Axle 3-Pass

Wheel1-On : Tire Tread Depth: 10 in
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 30 degrees • Brake Stroke: 1.5 in
Wheel2 : Tire Tread Depth: 10 in
Brake(1): No Brake
N/A
Wheel3-On : Tire Tread Depth: 13 in
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 30 degrees • Brake Stroke: 1.5 in



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71131

Station Name: TKC Trucking and Picker Service

Technician #: 90508

Technician Name: Derrick Ching

Signing Officer #: 85781

Signing Officer Name: Troy Ching

Customer Details:

Name: TKC Trucking and Picker Service Ltd.

Address: Box 2337, Kindersley, Saskatchewan, S0L 1S0

Vehicle Details:

VIN: 2A9LB4035CN125042

Hubometer Reading: 15903 km

Year: 2012

Vehicle Make/Model: ASPEN TRAILER ASPEN

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Wheel4 : Tire Tread Depth: 13 in
Brake(1): No Brake
N/A

PASS - vehicle passes inspection	Decal # P276523	Inspection Completed Date: 17Jul2026
----------------------------------	-----------------	--------------------------------------

Trailer and Semi-Trailer Inspection Certificate

VOID WITHOUT
DECAL

This Certificate is issued under the authority of the Province of Saskatchewan

Vehicle Standards and Inspection

Date Inspection Started 17 07 2026 day month year Date Inspection Completed 17 07 2026 day month year Inspection Expiry Date 30 06 2026 day month year Trailer ☒ Semi-Trailer ☐ Converter/Jeep/Pony/Booster ☐ Brake Type Air ☒ Hydraulic ☐ Electric ☐ Pass ☐ Fail ☐ Out-of-Service Condition ☐ FTR ☐ TLV ☐ PMVI ☒	INSPECTING STATION Station Number 71131 Station Name _____ City _____ Signing Officer Number 85781 Signing Officer Signature _____ Station Phone Number _____ Technician Number 90508 Technician Signature _____ PMP STATION DECAL ISSUED TO: PMP Station # _____ PMP Station Name _____ PMP Technician # _____ Technician Signature _____ Vehicle Owner: TKC TRUCKING AND PICKER SERVICES LTD. Address _____ City _____ Province _____ Postal Code _____ Phone _____ Licence Number 65J352 Prov AB Serial Number 2A9LB4035CN125042 Hubometer Reading 15903 km mi ☒ Hubom. Type ASPEN Make Trailer Model 2012 Year TL7 Unit #
---	---

Circle Items Requiring Attention
R = Item Rejected C = Item Corrected

No.	R	C	TRAILER EXTERIOR	Ref #	No.	R	C	TRAILER EXTERIOR	Ref #	No.	R	C	CHASSIS	Ref #
01			Vehicle Identification Number	5	10			Auxiliary Equipment	5	18			Sliding Axle Assembly (if equipped)	8
02			Lamps	6	11			Fire Extinguisher	5	19			Tires/Wheels	9
			Reflex Reflectors	6	12			Wheel Bearings	9	20			Frame/Crossmembers/Mounts	8
04			Retro Reflective Markings	6	13			Trailer Hitch	10	21			Suspension/Axles	2
05			Battery/Wiring Condition	7	14			Rear Impact Guard	8	22			Hyd Brake System/Components	3.1
06			Trailer Power Cord	7	15			Attached Equipment	8	23			Air Brake System/Components	3.2
07			Mudflaps/Fenders	8	16			Fuel System	1	24			Elec Brake System/Components	3.1
08			Landing Gear	8	17			Exhaust/Emission System	1	25			Self-Steering Axle	2 & 4
09			Cargo Bodies/Vessels	8										

Tire Tread Depth (in/mm) <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>Front</td><td>8 18 10</td><td>Rear</td></tr> <tr> <td></td><td>8 10 10</td><td></td></tr> <tr> <td></td><td>22 15 13</td><td></td></tr> <tr> <td></td><td>22 15 13</td><td></td></tr> </table>	Front	8 18 10	Rear		8 10 10			22 15 13			22 15 13		Drum Size/Rotor Thickness (in/mm) <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>Front</td><td></td><td>Rear</td></tr> <tr> <td></td><td></td><td></td></tr> </table> Brake Stroke (in/mm) <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>Front</td><td>1.5 1.5 1.5</td><td>Rear</td></tr> <tr> <td></td><td>1.5 1.5 1.5</td><td></td></tr> </table>	Front		Rear				Front	1.5 1.5 1.5	Rear		1.5 1.5 1.5		Brake Cam Rotation (degree) <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>Front</td><td>30° 30° 30°</td><td>Rear</td></tr> <tr> <td></td><td>30° 30° 30°</td><td></td></tr> </table>	Front	30° 30° 30°	Rear		30° 30° 30°		An "X" is placed in the box(es) below indicates a full brake inspection was performed with wheel(s) removed. Wheel Position <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>Front</td><td>☐</td><td>☐</td><td>☐</td><td>☐</td><td>☐</td><td>☐</td><td>Rear</td></tr> <tr> <td></td><td>☐</td><td>☐</td><td>☐</td><td>☐</td><td>☐</td><td>☐</td><td></td></tr> </table> Brake Lining Thickness (in/mm) <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>13/16</td><td>13/16</td><td>13/16</td><td>13/16</td><td>13/16</td><td>13/16</td></tr> </table>	Front	☐	☐	☐	☐	☐	☐	Rear		☐	☐	☐	☐	☐	☐		13/16	13/16	13/16	13/16	13/16	13/16
Front	8 18 10	Rear																																																					
	8 10 10																																																						
	22 15 13																																																						
	22 15 13																																																						
Front		Rear																																																					
Front	1.5 1.5 1.5	Rear																																																					
	1.5 1.5 1.5																																																						
Front	30° 30° 30°	Rear																																																					
	30° 30° 30°																																																						
Front	☐	☐	☐	☐	☐	☐	Rear																																																
	☐	☐	☐	☐	☐	☐																																																	
13/16	13/16	13/16	13/16	13/16	13/16																																																		

Record final accepted measurements in all areas above.

Remarks:

Vehicle received without repairs by:

Signature This inspection is not an authorization for repairs. Permission from the owner must be obtained.