

K22-3



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # P283462

Station #: 70740	Station Name: Sydia Bros Ent Ltd
Technician #: 92403	Technician Name: Brooke Starchuk
Signing Officer #: 91568	Signing Officer Name: Erica Durocher

Customer Details:	
Name: Sydia Bros Ent Ltd	Address: PO Box 2477 Stn Main, Lloydminster, Saskatchewan, S9V 1W5

Inspection Completed Date: 20May2026	Inspection Expiry Date: 31May2027
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 2A9LB4031VN125297	Hubometer Reading:
Year: 1997	Vehicle Make/Model: TRAILER/TRAILER
Plate: 742 NRC	Jurisdiction: Saskatchewan
Unit: 366S	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.
--

P283462





Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70740
Technician #: 92403
Signing Officer #: 91568

Station Name: Sydia Bros Ent Ltd
Technician Name: Brooke Starchuk
Signing Officer Name: Erica Durocher

Customer Details:
Name: Sydia Bros Ent Ltd

Address: PO Box 2477 Stn Main, Lloydminster, Saskatchewan, S9V

Vehicle Details:
VIN: 2A9LB4031VN125297
Year: 1997

Hubometer Reading:
Vehicle Make/Model: TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	rhs front dust cover. rhs rear dust cover. lhs rear slack pin.
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 11 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 8 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 mm • Cam Rotation: 55.0 degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 mm • Cam Rotation: 55.0 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 12 mm

Brake(1): No Brake

N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 10 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 mm • Cam Rotation: 55.0 degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 16 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 mm • Cam Rotation: 55.0 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 16 mm

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 5 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 8 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 mm • Cam Rotation: 55.0 degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 9 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 mm • Cam Rotation: 55.0 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 8 mm
Brake(1): No Brake
N/A

PASS - vehicle passes inspection

Decal # P283462

Inspection Completed Date: 20May2026