

314-17



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A391683

Station #: 71794

Station Name: 102128106 Saskatchewan Ltd.

Technician #: 89825

Technician Name: Warren Shkopich

Signing Officer #: 91652

Signing Officer Name: Donald Setrikov

Customer Details:

Name: 101189594 Saskatchewan LTD

Address: #14 Larocque dr, Meadow lake, Saskatchewan, S9X 2A1

Inspection Completed Date: 19Oct2026

Inspection Expiry Date: 31Oct2027

Vehicle Details:

VIN: 2PLB03432RBF19497

Hubometer Reading:

Year: 2024

Vehicle Make/Model: PEERLESS TRAILER/TRAILER

Plate: 267-NBH

Jurisdiction: Saskatchewan

Unit: 266-NBH

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71794

Station Name: 102128106 Saskatchewan Ltd.

Technician #: 89825

Technician Name: Warren Shkopich

Signing Officer #: 91652

Signing Officer Name: Donald Setrikov

Customer Details:

Name: 101189594 Saskatchewan LTD

Address: #14 Larocque dr, Meadow lake, Saskatchewan, S9X 2A1

Vehicle Details:

VIN: 2PLB03432RBF19497

Hubometer Reading:

Year: 2024

Vehicle Make/Model: PEERLESS TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
		x		Mud Flaps/Fenders (8)	Front mudflap ripped more than 2 inches
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
x				Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 6 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 6 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 7/8 in • Cam Rotation: 17.0 degrees • Brake Stroke: 1 7/16 in

Wheel3-On : Tire Tread Depth: 15 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 7/8 in • Cam Rotation: 17.0 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 15 mm

Brake(1): No Brake

N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 13 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 13 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 7/8 in • Cam Rotation: 18.0 degrees • Brake Stroke: 1 7/16 in

Wheel3-On : Tire Tread Depth: 10 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 7/8 in • Cam Rotation: 17.0 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 10 mm

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 11 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 7/8 in • Cam Rotation: 17.0 degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 6 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 7/8 in • Cam Rotation: 18.0 degrees • Brake Stroke: 1 7/16 in

Wheel4 : Tire Tread Depth: 6 mm

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A391683

Inspection Completed Date: 19Oct2026