T19-1

SGI

Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A391656

Station #: 71794

Station Name: 102128106 Saskatchewan Ltd.

Technician #: 89825

Technician Name: Warren Shkopich

Signing Officer #: 91652

Signing Officer Name: Donald Setrikov

Customer Details:

Name: Canoe Lake RDI

Address: P.O Box 231, Canoe Narrows, Saskatchewan, S0M-0KO

Inspection Completed Date: 01Oct2026

Inspection Expiry Date: 30Apr2027

Vehicle Details:

VIN: 1XKWD40XXGR978728

Odometer Reading: 971795 km

Year: 2016

Vehicle Make/Model: KENWORTH/HEAVY VEHICLE

Plate: 484-NFZ

Jurisdiction: Saskatchewan

Unit: 2107

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.

SGI

Vehicle Standards and Inspection

Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71794

Station Name: 102128106 Saskatchewan Ltd.

Technician #: 89825

Technician Name: Warren Shkopich

Signing Officer #: 91652

Signing Officer Name: Donald Setrikov

Customer Details:

Name: Canoe Lake RDI

Address: P.O Box 231, Canoe Narrows, Saskatchewan, S0M-0KO

Vehicle Details:

VIN: 1XKWD40XXGR978728

Odometer Reading: 971795 km

Year: 2016

Vehicle Make/Model: KENWORTH HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
		x		Clutch/Clutch Pedal (1)	Fork tips broken inside transmission

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	No cab lights
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
		x		Body/Bumpers (8)	One bumper locking bolt missing at front bumper
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
		x		Mud Flaps/Fenders (8)	Number two axle right hand side mudflap missing
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
		x		Cab/Hood Safety Catches (8)	Hood bottom hinges are loose
x				Power Steering System (4)	
x				Fuel System (1)	
		x		Battery/Wiring Condition (7)	Electrical junction box hanging
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments

x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	Number three axle right hand side clevis bent back and push rod bent also, ABS wires severed, slack tube U bolts loose
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
		x		Suspension/Axles (2)	Number 3 axle right hand torsion bushing missing, number two axle both walking beam bushings are wore out, number two axle both walking beams bushings wore out
x				Drive Shaft/Universal Joints (1)	
		x		Exhaust/Emission System (1)	bellows pipe wore through

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 7.68 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 69.0 degrees • Brake Stroke: 1 7/16 in
Wheel2-On : Tire Tread Depth: 5.80 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 72.0 degrees • Brake Stroke: 1 7/16 in

Axle 2-Pass

Wheel1 : Tire Tread Depth: 7 mm
Brake(1): No Brake
N/A
Wheel2-On : Tire Tread Depth: 7 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 7/8 in • Cam Rotation: 18.0 degrees • Brake Stroke: 1 1/4 in
Wheel3-On : Tire Tread Depth: 5 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 7/8 in • Cam Rotation: 17.0 degrees • Brake Stroke: 1 1/4 in
Wheel4 : Tire Tread Depth: 5 mm
Brake(1): No Brake
N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 11 mm
Brake(1): No Brake
N/A
Wheel2-On : Tire Tread Depth: 11 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 57.0 degrees • Brake Stroke: 1 3/8 in
Wheel3-On : Tire Tread Depth: 10 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 71.0 degrees • Brake Stroke: 1 9/16 in

Wheel4 : Tire Tread Depth: 10 mm
Brake(1): No Brake
N/A

PASS - vehicle passes inspection	Decal # A391656	Inspection Completed Date: 01Oct2026